

Name: Milton Historic District (streetscape A: west, southwest along Broad Street; site #114 at extreme right)

Location: Milton, Sussex County, Delaware Photographer: photograph by survey staff Date of Photograph:

Location of Negative: Division of Historical & Cultural Affairs, Bureau of Archaeology & Historic Preservation, Dover, DE

Description: view from east-northeast Photograph Number: / of




Name: Milton Historic District (streetscape B: north along Union Street, across Chandler Street, intersection; site # 93 at extreme right)

Location: Milton, Sussex County, Delaware

Photographer: photograph by survey staff Date of Photograph:

Location of Negative: Division of Historical & Cultural Affairs, Bureau of Archaeology & Historic Preservation, Dover, DE

Description: view from south Photograph Number: Z of 38



Name: Milton Historic District (streetscape C: Union Street, northwest from Front Street intersection; site # 86 at extreme right)

Location: Milton, Sussex County, Delaware

Photographer: photograph by survey staff Date of Photograph:

Location of Negative: Division of Historical & Cultural Affairs, Bureau of Archaeology & Historic Preservation, Dover, DE

Descripton: view from northeast Photograph Number: 3 of 37



Name: Milton Historic District (streetscape D: east, side of Federal Street; northeast acorss Chandler Street intersection; site #83 at extreme right)

Location: Milton, Sussex County, Delaware Photographer: photograph by survey staff Date of Photograph:

Location of Negative: Division of Historical & Cultural
Affairs, Bureau of Archaeology &
Historic Preservation, Dover, DE

Description: view from northeast Photograph Number: 4 of 25



Name: Milton Historic District (streetscape E: eastnortheast along Mill Street from site 135)

Location: Milton, Sussex County, Delaware

Photographer: photograph by survey staff
Date of Photograph:
Location of Negative: Division of Historical & Cultural
Affairs, Bureau of Archaeology &
Historic Preservation, Dover, DE

Description: view from west-southwest Photograph Number: 5 of 38



Name: Milton Historic District (streetscape F: east side of Federal Street, south-southeast across Coulter Street intersection; site #77 at extreme left)

Location: Milton, Sussex County, Delaware

Photographer: photograph by survey staff Date of Photograph:

Location of Negative: Division of Historical & Cultural Affairs, Bureau of Archaeology & Historic Preservation, Dover, DE

Description: view from north-northeast Photograph Number: 4 of 34



Name: Milton Historic District (streetscape G: east side of Federal Street, north-northeast from Poplar Street intersection; site #63 at extreme right)

Location: Milton, Sussex County, Delaware Photographer: photograph by survey staff Date of Photograph:

Location of Negative: Division of Historical & Cultural Affairs, Bureau of Archaeology & Historic Preservation, Dover, DE

Description: view from north-northeast Photograph Number: 7 of



Name: Milton Historic District (Clendaniel house, site #9)
Location: (338 Union Street), Milton, Sussex County,

Dover, Delaware

Photographer: photograph by survey staff
Date of Photograph: 8/27/79
Location of Negative: Division of Historical & Cultural
Affairs, Bureau of Archaeology &
Historic Preservation, Dover, DE

Description: view from southeast Photograph Number: % of %%



Name: Milton Historic District (Lingo house, site site #10)

Location: (334 Union Street) Milton, Sussex County,
Delaware

Photographer: photograph by survey staff Date of Photograph: 8/27/79

Location of Negative: Division of Historical & Cultural Affairs, Bureau of Archaeology & Historic Preservation, Dover, DE

Description: view from southeast

Flotograph #: 9 of 38



Location: (326 Union Street), Milton, Sussex County, Delaware

Photographer: photograph by survey staff Date of Photograph: 8/27/79

Location of Negative: Division of Historical & Cultural Affairs, Bureau of Archaeology & Historic Preservation, Dover, DE

Descripton: view from northeast Photograph Number: of 38



Name: Milton Historic District (Betts house, site #14) Location: (326 Union Street), Milton, Sussex County, Delaware Photographer: photograph by survey staff Date of Photograph: 8/27/79 Location of Negative: Division of Historical & Cultural

Affairs, Bureau of Archaeology & Historic Preservation, Dover, DE Description: detail view from east-northeast

Photograph Number: // of 38



Name: Milton Historic District (Capt. Russell house, site #15)
Location: (322 Union Street), Milton, Sussex County, Delaware
Photographer: photograph by survey staff
Date of Photograph: 8/28/79

Location of Negative: Division of Historical & Cultural
Affairs, Bureau of Archaeology &
Historic Preservation, Dover, DE
Description: view from west

Photograph Number: 12 of 38



Name: Milton Historic District (Carey Store, site #21)
Location: (302) Union Street) Milton, Sussex County,
Delaware
Photographer: photograph by survey staff
Date of Photograph: 8/27/79

Location of Negative: Division of Historical & Cultural
Affairs, Bureau of Archaeology &
Historic Preservation, Dover, DE
Description: view from southeast

Photograph Number: /3 of 38



Name: Milton Historic District (Atkins House & Store site #22)

Location: (220-222 Union Street), Milton, Sussex County,
Delaware
Photographer: photograph by survey staff

Photographer: photograph by survey staff Date of Photograph: 8/27/79 Location of Negative: Division of Historic

Location of Negative: Division of Historical & Cultural
Affairs, Bureau of Archaeology &
Historic Preservation, Dover, DE

Description: view from north Photograph Number: /4 of 38



Location: (106 Union Street), Milton, Sussex County, Delaware

Photographer: photograph by survey staff Date of Photograph: 8/27/79

Location of Negative: Division of Historical & Cultural Affairs, Bureau of Archaeology & Historic Preservation, Dover, DE

Description: view from northeast Photograph Number: /5 of 38



Name: Milton Historic District (McGee house, site #32)

Location: (102 Union Street), Milton, Sussex County Delaware

Photographer: photograph by survey staff
Date of Photograph: 8/27/79
Location of Negative: Division of Historical & Cultural
Affairs, Bueau of Archaeology &

Historic Preservation, Dover, DE

Description: view from north Photograph Number: //_ of 3%



Name: Milton Historic District (Draper-Atkins house, site #39)

Location: (206 Federal Street), Milton, Sussex County, Delaware

Photographer: photograph by survey staff Date of Photograph: 8/27/79

Location of Negative: Division of Historical & Cultural
Affairs, Bureau of Archaeology &
Historic Preservation, Dover, DE

Descripton: view from southeast Photograph Number: /7 of 3%



Name: Milton Historic District (Ca. 1875 house, site #44)

Location: (308 Federal Street), Milton, Sussex County,
Delaware
Photographer: photograph by survey staff
Date of Photograph: 8/27/79
Location of Negative: Division of Historical & Cultural

Affairs, Bureau of Archaeology & Historic Preservation, Dover, De

Description: view from southeast Photograph Number: // of 35/



Name: Milton Historic District (Gov. Hazzard office) site #52)

Location: (rear of 410 Federal Street), Milton, Sussex County, Delaware

Photographer: photograph by survey staff Date of Photograph: 9/11/79

Location of Negative: Division of Historical & Cultural Affairs, Bureau of Archaeology & Historic Preservation, Dover, DE

Description: view from south-southeast

Photograph Number:



Name: Milton Historic District (Gov. Ponder mansion, site #54)

Location: (416 Federal Street), Milton, Sussex County, Delaware

Photographer: photograph by survey staff Date of Photograph: 8/27/79

Location of Negative: Division of Historical & Cultural
Affairs, Bureau of Archaeology &

Historic Preservation, Dover, DE

Description: view from southeast Photograph Number: of 3%



Name: Milton Historic District (Modified bungalow, site #58)

Location: (424 Federal Street), Milton, Sussex County,
Delaware
Photographer: photograph by survey staff
Date of Photograph: 8/27/79
Location of Negative: Division of Historical & Cultural
Affairs, Bureau of Archaeology &

Historic Preservation, Dover, DE

Descripton: view from east Photograph Number: 21 of 38



Name: Milton Historic District (Ca. 1900 Queen Ann house, site #63)

Location: (417 Federal Street), Milton, Sussex County, Delaware

Photographer: photograph by survey staff Date of Photograph: 8/27/79

Location of Negative: Division of Historical & Cultural
Affairs, Bureau of Archaeology &
Historic Preservation, Dover DE

Description: view from west-northwest Photograph Number: 77 of 24



Name: Milton Historic District (St. John the Baptist, site #71)

Location: (307 Federal Street), Milton, Sussex County,
Delaware
Photographer: photograph by survey staff

Date of Photograph: 8/27/79

Location of Negative: Division of Historical & Cultural
Affairs, Bureau of Archaeology &
Historic Preservation, Dover, DE

Description: view from west-northwest Photograph Number: 23 of 38



Name: Milton Historic District (M.E. Parsonage, site 74)

Location: (301 Federal Street), Milton, Sussex County, Delaware

Photographer: photograph by survey staff

Date of Photograph: 8/27/79

Location of Negative: Division of Historical & Cultural Affairs, Bureau of Archaeology & Historic Preservation. Dover. DE

Description: view from northwest Photograph Number: 74 of 38



Name: Milton Historic District (Prettyman house, site #77)

Location: (203 Federal Street), Milton, Sussex County,
Delaware

Photographer: photograph by survey staff Date of Photograph: 8/27/79

Location of Negative: Division of Historical & Cultural
Affairs, Bureau of Archaeology &
Historic Preservation, Dover, DE

Description: view from northwest Photograph Number: 25 of 38



Name: Milton Historic District (Dr. Hopkins house, site #78)

Location: (201 Federal Street), Milton, Sussex County, Delaware

Photographer: photograph by survey staff Date of Photograph: 8/27/79

Location of Negative: Division of Historical & Cultural
Affairs, Bureau of Archaeology &
Historic Preservation, Dover, De

Description: view from northwest Photograph Number: 7 of 38



Name: Milton Historic District (Burton house, site #80)

Location" (117 Federal Street), Milton, Sussex County,
Delaware
Photographer: photograph by survey staff

Date of Photograph: 8/27/79

Location of Negative: Division of Historical & Cultural Affairs, Bureau of Archaeology & Historic Preservation, Dover DE

Descripton: view from west-northwest Photograph Number: 27 of 38



Name: Milton Historic District (Samuel's Dept. Store & Ye Ole Good News Store, site #s 86 & 87)

Location: (105-7 Federal Street), Milton, Sussex County, Delaware

Photographer: photograph by survey staff Date of Photograph: 9/11/79

Location of Negative: Division of Historical & Cultural
Affairs, Bureau of Archaeology &
Historic Preservation, Dover, DE

Description: view from south

Photograph Number: 27 of 38



Name: Milton Historic District (Betts building, site #90)

Location: (125 Union Street), Milton, Sussex County, Delaware

Photographer: photograph by survey staff Date of Photograph: 8/80

Location of Negative: Division of Historical & Cultural Affairs, Bureau of Archaeology & Historic Preservation

Description: view from south Photograph Number: 29 of 38



Name: Milton Historic District (Welch Home & Drug, site #94)

Location: (205 Union Street), Milton, Sussex County, Delaware

Photographer: photograph by survey staff

Date of Photograph: 8/27/79

Location of Negative: Division of Historical & Cultural Affairs, Bureau of Archaeology &

Historic Preservation, Dover, DE

Description: view from south Photograph Number: of 3%



Name: Milton Historic District (Carey Mansion, site #99)

Location: (301 Union Street), Milton, Sussex County, Delaware

Photographer: photograph by survey staff

Date of Photograph: 8/27/79

Location of Negative: Division of Historical & Cultural Affairs, Bureau of Archaeology & Historic Preservation, Dover, De

Description: view from southwest Photograph Number: 7/ of 39



Name: Milton Historic District (Warren house, site #102)

Location: (311 Union Street), Milton, Sussex County, Delaware

Photographer: photograph by survey staff

Date of Photograph: 9/11/79

Location of Negative: Division of Historical & Cultual Affairs, Bureau of Archaeology & Historic Preservation

Description: view from south Photograph Number: 32 of 38



Name: Milton Historic District (19th Century structure, site #103)

Location: (313 Union Street), Milton, Sussex County, Delaware

Photographer: photograph by survey staff Date of Photograph: 8/27/79

Location of Negative: Division of Historical & Cultural
Affairs, Bureau of Archaeology &
Historic Preservation, Dover, DE

Descripton: view from south-southwest Photograph Number: 33 of 38



Name: Milton Historic District (Ca. 1870 house, site #114)

Location: (106 Broad Street), Milton, Sussex County Delaware

Photographer: photograph by survey staff
Date of Photograph: 4/80
Location of Negative: Division of Historical & Cultura
Affairs, Bureau of Archaeology &

Location of Negative: Division of Historical & Cultural Affairs, Bureau of Archaeology & Historic Preservation, Dover, De Description: view from southwest

Photograph Number: 34 of 38



Name: Milton Historic District (Ca. 1870 house, site #142)

Location: (316 Mill Street), Milton, Sussex County, Delaware

Photographer: photograph by survey staff Date of Photograph: 4/80

Location of Negative: Division of Historical & Cultural Affairs, Bureau of Archaeology & Historic Preservation, Dover, DE

Description: view from northeast

Photograph Number: 35 of 38



Name: Milton Historic District (Ca. 1840 house, site #144)

Location: (317 Mill Street), Milton, Sussex County, Delaware

Photographer: photograph by survey staff Date of Photograph: 4/80

Location of Negative: Division of Historical & Cultural Affairs, Bureau of Archaeology & Historic Preservation, Dover, DE

Description: detail view from southeast Photograph Number: $\frac{1}{2}$ of $\frac{1}{2}$



Name: Milton Historic District (Ca. 1830 house, site #146)

Location: (313 Mill Street), Milton, Sussex County, Delaware

Photographer: photograph by survey staff Date of Photograph: 4/80

Location of Negative: Division of Historical & Cultural Affairs, Bureau of Archaeology & Historic Preservation, Dover, DE

Description: view from south-southeast Photograph Number: \$7 of \$\$\times\$\$



Name: Milton Historic District (Endeavor Lodge #17, site #153)

Location: (117 Chestnut Street), Milton, Sussex County,
Delaware

Photographer: photograph by survey staff

Date of Photograph: 4/80

Location of Negative: Division of Historical & Cultural Affairs, Bureau of Archaeology & Historic Preservation, Dover, DE

Description: view from southwest Photograph Number: 37 of 37