KENTUCKY	HISTORIC	RESOURCES
Individ	ual Invento	ry Form

Resource # 165 Shelby County Shelby

2929.

1. Name of Resource:	16. Date:
Logan House	Original Building
2. Original Owner:	Addition 1970
James Knox Logan (?)	17. Style:
3. Other Names:	Vernacular
Oxford	
4. Prehistoric Site × Building Object	18. Architect/Builder:
Historic Site Structure Other	Unknown
5. Location: North side of Brunerstown Rd.,	19. No. of Stories: 2
east side of Bullskin Creek	20. Original Floor Plan: Center passage
6. Owner's Name:	21. Single Pile Do
	22. Roof Form & Mater
Dr. Richard N. Redinger [ P ]	Hipped, standing s
7. Owner's Address:	23. Structural Material
	Brick
16601 Taylorsville Rd., Louisville, KY	24. Exterior Material:
8. Evaluation: National Register [ N ]	<u>bond facade</u> , comm
9. Recognition & Date:	25. Foundation Materia
Nat.Landmark Local Landmark	Stone, ashlar front
Nat.RegisterHABS/HAERHighway MarkerKY Inventory 5-28-74	26. Major Alterations: Moved/Rebuilt
KY Landmark Certificate 3-11-71	× Additions
10. N.R.Status & Date:	27. Special Features:
11. N.R.Group:	None
District Name: []	28. Outbuildings: fra
Mult.Resource Area: Shelby County [ ]	28. Outbuildings: fra Brick Kitchen, ston
Thematic Name: []	29. Original Function:
12. Historical Theme:	<u>Residential/Domes</u>
Primary: Architecture [030]	30. Present Use:
Secondary: []	As above 31. Condition:
Other:     []]       13. Statement of Significance:	Excellent
	32. Endangered:
This property is significant under criterion C	vi. Indungered.
as a well-preserved example of the mid-19th	33. Attach Photos:
century (1840-65) brick, 2-story, center-	Roll: Photo No
passage, double-pile plan in Shelby County.	
Only six such structures were identified from	
the period, the majority of which l C ]	13 2 - 13
14. History:	
House appears to have been built ca. 1860 by	
a descendant of Kentucky pioneer Benjamin	
Logan who settled on this site in 1794 on a	
1,000-acre land grant. Logan is said to have	
built a house and grist mill on the site and	
lived here until his deathin 1802. Present hous	5.0
remained in Logan family until ca 1882.	
From ca. 1890 until 1904, it was owned by	
	·
Patrick Joyes, who had built the Joyesdale	
Station and post office on the nearby Southern	
Railroad and the Joyes Station Road which 15. Source of historical information and/or contact	34. Prepared by: C. V
person: 1979 KY Historic Resources Inventory	
Form; files of KY Heritage Council; "Exciting	35. Organization: V, S 36. Date: April 1986
History In 'Oxford', Logan Home," The Senti-	36. Date: April 1986 37. New Survey
<u>nel-News</u> , Shelbyville, KY, Jan. 27, 1972.	Ji. New Burvey
<u>mer-wews</u> , shebyville, Kr, Jan. 27, 1972.	

ntory Form	<u> </u>	helby	County	y
16. Date: Original Bu	ilding ca.	1860	[6]	- ]
Addition			[2]	]
17. Style:				-
Vernacular			[ 3V ]	]
18. Architect/Bui	lder:			
Unknown				=
19. No. of Stories	the second se		[2.0]	l
20. Original Floor		•		
<u>Center passag</u>		D21 -	ICP	J
21. Single Pile			N.A.	-
22. Roof <u>Form</u> &			inal <u>x</u>	-
<u>Hipped, stand</u> 23. Structural Ma	torial	mede lorig	1081	-
Brick	teriar.		[в	1
	rial: Brick	ninnin		i
24. Exterior Mate	COMMON W	Flemich	bonhing	-
25. Foundation Ma	aterial:	1 19111311	Somethy S	21
<u>Stone</u> , ashlar		es course	d [S	]
26. Major Alterat		None		-
Moved/Reb		Other		
<b>X</b> Additions				
27. Special Featu	res:		······································	-
None				
28. Outbuildings:	frame o	utbldgfr	ame smok	- -
		utbldgfra house,	ame smok	f
<ol> <li>28. Outbuildings: Brick Kitchen,</li> <li>29. Original Func</li> </ol>	tion:			-
29. Original Func	tion:			-
29. Original Func <u>Residential/D</u> 30. Present Use:	tion:		ell [0]A	]
29. Original Func Residential/D 30. Present Use: As above	tion:			]
<ul> <li>29. Original Func Residential/D</li> <li>30. Present Use: As above</li> <li>31. Condition:</li> </ul>	tion:		<u>ell [0]A</u> [01A ]	]
<ul> <li>29. Original Func Residential/D</li> <li>30. Present Use: As above</li> <li>31. Condition: Excellent</li> </ul>	tion:	single dw	<u>ell [0]A</u> [01A ] [ E	]
<ul> <li>29. Original Func Residential/D</li> <li>30. Present Use: As above</li> <li>31. Condition: Excellent</li> </ul>	tion:	single dw	<u>ell [0]A</u> [01A [ E Yes	]
<ul> <li>29. Original Func Residential/D</li> <li>30. Present Use: As above</li> <li>31. Condition: Excellent</li> <li>32. Endangered:</li> </ul>	tion: omestic	single dw	<u>ell [0]A</u> [01A ] [ E	]
<ol> <li>Original Func <u>Residential/D</u></li> <li>Present Use: <u>As above</u></li> <li>Condition: <u>Excellent</u></li> <li>Endangered:</li> <li>Attach Photos</li> </ol>	tion: omestic, s	single dw	ell [0]A [01A] [ E Yes No	]
<ol> <li>Original Func <u>Residential/D</u></li> <li>Present Use: <u>As above</u></li> <li>Condition: <u>Excellent</u></li> <li>Endangered:</li> <li>Attach Photos</li> </ol>	tion: omestic	single dw	ell [0]A [01A] [ E Yes No	]
<ul> <li>29. Original Func <u>Residential/D</u></li> <li>30. Present Use: <u>As above</u></li> <li>31. Condition: <u>Excellent</u></li> <li>32. Endangered:</li> <li>33. Attach Photos Roll: Photos</li> </ul>	tion: omestic, s s: oto Nos:	Single dw	ell [0]A [01A] [ E Yes No	]
<ol> <li>29. Original Func <u>Residential/D</u></li> <li>30. Present Use: <u>As above</u></li> <li>31. Condition: <u>Excellent</u></li> <li>32. Endangered:</li> <li>33. Attach Photos Roll: Photos</li> </ol>	tion: omestic, s	single dw	ell [0]A [01A] [ E Yes No	]
<ol> <li>29. Original Func <u>Residential/D</u></li> <li>30. Present Use: <u>As above</u></li> <li>31. Condition: <u>Excellent</u></li> <li>32. Endangered:</li> <li>33. Attach Photos Roll: Photos</li> </ol>	tion: omestic, s s: oto Nos:	Single dw	ell [0]A [01A] [ E Yes No	]
<ol> <li>Original Func <u>Residential/D</u></li> <li>Present Use: <u>As above</u></li> <li>Condition: <u>Excellent</u></li> <li>Endangered:</li> <li>Attach Photos Roll: Photos</li> </ol>	tion: omestic, s s: oto Nos:	Single dw	ell [0]A [01A] [ E Yes No	]
<ol> <li>Original Func <u>Residential/D</u></li> <li>Present Use: <u>As above</u></li> <li>Condition: <u>Excellent</u></li> <li>Endangered:</li> <li>Attach Photos Roll: Photos</li> </ol>	tion: omestic, s s: oto Nos:	Single dw	ell [0]A [01A] [ E Yes No	]
<ol> <li>Original Func <u>Residential/D</u></li> <li>Present Use: <u>As above</u></li> <li>Condition: <u>Excellent</u></li> <li>Endangered:</li> <li>Attach Photos Roll: Photos</li> </ol>	tion: omestic, s s: oto Nos:	Single dw	ell [0]A [01A] [ E Yes No	]
<ol> <li>Original Func <u>Residential/D</u></li> <li>Present Use: <u>As above</u></li> <li>Condition: <u>Excellent</u></li> <li>Endangered:</li> <li>Attach Photos Roll: Photos</li> </ol>	tion: omestic, s s: oto Nos:	Single dw	ell [0]A [01A] [ E Yes No	]
<ol> <li>Original Func <u>Residential/D</u></li> <li>Present Use: <u>As above</u></li> <li>Condition: <u>Excellent</u></li> <li>Endangered:</li> <li>Attach Photos Roll: Photos</li> </ol>	tion: omestic, s s: oto Nos:	Single dw	ell [0]A [01A] [ E Yes No	]
<ul> <li>29. Original Func Residential/D</li> <li>30. Present Use: <u>As above</u></li> <li>31. Condition: Excellent</li> <li>32. Endangered:</li> <li>33. Attach Photos Roll: Photos</li> <li>13 2</li> </ul>	tion: omestic, s s: oto Nos:	Single dw	ell [0]A [01A] [ E Yes No	]
<ul> <li>29. Original Func <u>Residential/D</u></li> <li>30. Present Use: <u>As above</u></li> <li>31. Condition: <u>Excellent</u></li> <li>32. Endangered:</li> <li>33. Attach Photos Roll: Photose</li> <li>13 2</li> </ul>	tion: omestic, s s: oto Nos:	Single dw	ell [0]A [01A] [ E Yes No	]
<ul> <li>29. Original Func <u>Residential/D</u></li> <li>30. Present Use: <u>As above</u></li> <li>31. Condition: <u>Excellent</u></li> <li>32. Endangered:</li> <li>33. Attach Photos Roll: Photose</li> <li>13 2</li> </ul>	tion: omestic, s s: oto Nos:	Single dw	ell [0]A [01A] [ E Yes No	]
<ul> <li>29. Original Func <u>Residential/D</u></li> <li>30. Present Use: <u>As above</u></li> <li>31. Condition: <u>Excellent</u></li> <li>32. Endangered:</li> <li>33. Attach Photos Roll: Photose</li> <li>13 2</li> </ul>	tion: omestic, s s: oto Nos:	Single dw	ell [0]A [01A] [ E Yes No	]
<ul> <li>29. Original Func <u>Residential/D</u></li> <li>30. Present Use: <u>As above</u></li> <li>31. Condition: <u>Excellent</u></li> <li>32. Endangered:</li> <li>33. Attach Photos Roll: Photos</li> </ul>	tion: omestic, s s: oto Nos:	Single dw	ell [0]A [01A] [ E Yes No	]
<ul> <li>29. Original Func <u>Residential/D</u></li> <li>30. Present Use: <u>As above</u></li> <li>31. Condition: <u>Excellent</u></li> <li>32. Endangered:</li> <li>33. Attach Photos Roll: Photose</li> <li>13 2</li> </ul>	tion: omestic, s s: oto Nos:	Single dw	ell [0]A [01A] [ E Yes No	]
<ul> <li>29. Original Func Residential/D</li> <li>30. Present Use: <u>As above</u></li> <li>31. Condition: Excellent</li> <li>32. Endangered:</li> <li>33. Attach Photos Roll: Photos</li> <li>13 2</li> </ul>	tion: omestic, s s: oto Nos:	Single dw	ell [0]A [01A] [ E Yes No	]
<ul> <li>29. Original Func Residential/D</li> <li>30. Present Use: <u>As above</u></li> <li>31. Condition: Excellent</li> <li>32. Endangered:</li> <li>33. Attach Photos Roll: Photos</li> <li>13 2</li> </ul>	tion: omestics	No. of S	ell [0]A [01A] [ E Yes No	]

Resurvey x

### KENTUCKY HISTORIC RESOURCES Individual Inventory Form

**Resource #** 165



## 13. Statement of Significance: (continued)

appear to have been built in the 1850's and 1860's and display pilasters, deep, bracketted cornices, and either double or triple windows. This site also contains a fine collection of outbuildings, including a brick kitchen/servants quarters, a frame meat house, a battered, coursed rubble ice house, and a frame outbuilding. Alterations to house have not seriously effected its significant plan and details. The 14. History: (continued) unusual collection of outbuildings demonstrates the layout of domestic space during the period of significance. The ice house is one of few in county.

connects Brunerstown Road with U.S. 60 two miles to the north. In 1904, the house was sold to Charles H. Ware, whose family sold to S.H. Price in 1970. The present owner is in the process of conducting a sympathetic restoration. Research seems to indicate that the house was probably built by James Knox Logan, a grandson of pioneer Benjamin Logan.

### 45. Description and House Plan: (continued)

in coursed rubble foundation side walls. Ashlar foundation on principal front except in central bay where concealed originally by a 2-story porch, replaced by a 1-story porch across the entire front (now removed also).

<u>Interior</u>: East range of rooms connected by pocket door; both have arched pilastered mantels and plaster ceiling medallions. Noith room has window to north of tripartite form which has hinged apron in central opening to form door to north porch. Splayed reveals and panelled aprons throughout the first floor. Center passage has ceiling medallion, earred doors with cornices. Stair curves against curved walls, has turned balusters. Rooms to east of passage have plainer pilastered mantels. Two-story ell altered although parapet roof may be original, adjacent two-story porch of L shape (original) has been enclosed on both floors. Originally porch had two-storysquare columns. Winder stair remains on angle of ell (original). Wide one-story porch across south front was added in late 19th century, now removed. Early stone steps from original porch remain in front of door.

<u>Outbuildings</u>: One-story two-room brick kitchen (?) to immediate northwest of ell has wood lintels, 6/6 sash, similar brick bond to house, west room has massive stone hearth and large fireplace in central chimney. Adjacent room mave have served as servants' quarters or as another service room. Immediately to the west of the kitchen stands a frame vertical board smokehouse, and directly north of the kitchen stands a deep stone icehouse with squatapered wallsnarrowing to the bottom. It has a later frame gabled roof. Between it and the kitchen stands a frame vert. board gabled outbuilding. with a projecting gable sheltering the north door.

The nominated area includes five contributing buildings.

#### 44. Site Plan (and Boundary Description & Justification for N.R. Sites):

Point A is located on the front (southern) yard fence at its intersection with a line extended southward from the eastern edge of the drive at that point where the drive turns eastward. Point A is 200 feet south/southeast of the southeastern corner of the dwelling.

#### UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES EVALUATION/RETURN SHEET

**REQUESTED ACTION: NOMINATION** 

PROPERTY Logan House NAME:

MULTIPLE Shelby County MRA NAME:

STATE & COUNTY: KENTUCKY, Shelby

DATE RECEIVED: 11/15/88 DATE OF PENDING LIST: 11/29/88 DATE OF 16TH DAY: 12/15/88 DATE OF 45TH DAY: 12/30/88 DATE OF WEEKLY LIST:

**REFERENCE NUMBER: 88002929** 

NOMINATOR: STATE

**REASONS FOR REVIEW:** 

APPEAL:NDATAPROBLEM:NLANDSCAPE:NLESSTHAN 50 YEARS:NOTHER:NPDIL:NPERIOD:NPROGRAM UNAPPROVED:NREQUEST:NSAMPLE:NSLRDRAFT:N

COMMENT WAIVER: N

ACCEPT

RETURN

\_REJECT \_\_\_\_\_\_\_\_\_\_ DATE

1979 - 1980 - 1980 - 1989 1972 - 1996 - 1996 - 1997 - 199

ABSTRACT/SUMMARY COMMENTS:

RECOM./CRITERIA\_\_\_\_\_ REVIEWER\_\_\_\_\_\_ DISCIPLINE\_\_\_\_\_ DATE\_\_\_\_\_

DOCUMENTATION see attached comments Y/N see attached SLR Y/N

# CLASSIFICATION

\_\_\_\_\_count \_\_\_\_resource type

STATE/FEDERAL AGENCY CERTIFICATION

FUNCTION

historic \_\_\_\_current

DESCRIPTION

\_\_\_\_architectural classification \_\_\_\_materials \_\_\_\_descriptive text

## SIGNIFICANCE

Period Areas of Significance--Check and justify below

Specific dates Builder/Architect Statement of Significance (in one paragraph)

summary paragraph
completeness
clarity
applicable criteria
justification of areas checked
relating significance to the resource
context
relationship of integrity to significance
justification of exception
other

.

BIBLIOGRAPHY
GEOGRAPHICAL DATA
acreageverbal boundary description UTMsboundary justification
ACCOMPANYING DOCUMENTATION/PRESENTATION
sketch mapsUSGS mapsphotographspresentation
OTHER COMMENTS
Questions concerning this nomination may be directed to
Phone
Signed Date