



RESTRICTED PARKING

OFFICIAL AUTHORIZED VEHICLES ONLY
ALL VEHICLES IN PARKING ARE SUBJECT TO THE RULES & REGULATIONS OF
THE CITY OF BOSTON (NO TOLLS)
UNAUTHORIZED USE OF THIS AREA MAY RESULT
IN A FINE OR OTHER PENALTY.

U.S. Post Office

Douglas Co.

FEDERAL OFFICE BUILDING

ROSEBURG, OREGON

MAIN (SOUTH) FACADE LOOKING NORTH

JUN 18 1979

KRISTINE BAK, OPERATIONAL PLANNING STAFF 6/78

GSA REGIONAL HEADQUARTERS, REGION 10

MAY 23 1979

PHOTOGRAPH # 1 OF 9



RESTRICTED PARKING
OFFICIAL AUTHORIZED VEHICLES ONLY
ALL VEHICLES EXCEPTING OFFICIAL AUTHORIZED
VEHICLES MUST BE THE PROPERTY OF THE CITY OF
LOS ANGELES AND MUST BE REGISTERED WITH THE
DEPARTMENT OF PUBLIC WORKS AND BE SUBJECT
TO A FINE OR OTHER PENALTY.

U.S. Post Office Douglas Co,
FEDERAL OFFICE BUILDING ROSEBURG, OREGON

EAST FACADE LOOKING NORTHWEST JUN 18 1979

KRISTINE BAK, OPERATIONAL PLANNING STAFF 6/78

GSA REGIONAL HEADQUARTERS, REGION 10

PHOTOGRAPH # 2 OF 9

MAY 23 1979



U.S. Post Office

Douglas Co.

FEDERAL OFFICE BUILDING ROSEBURG, OREGON

NORTH (REAR) & WEST FACADES LOOKING SOUTH

KRISTINE BAK, OPERATIONAL PLANNING STAFF 6/78

GSA REGIONAL HEADQUARTERS, REGION 10

PHOTOGRAPH # 3

JUN

OF

~~18~~⁹ 1979

MAY 23 1979



U.S. Post Office

Doyle
C

FEDERAL OFFICE BUILDING ROSEBURG, OREGON

UNDER CONSTRUCTION 9/13/17 LOOKING NORTH


PHOTOGRAPHER UNKNOWN

LOCATION OF NEGATIVE UNKNOWN

MAY 23 1979

PHOTOGRAPH # 4 OF 9

JUN 18 1979



U.S. Post Office

Douglas
County

FEDERAL OFFICE BUILDING ROSEBURG, OREGON

12/1/17 C.M. STEBINGER AND J.A. KIRK ON STEPS

PHOTOGRAPHER UNKNOWN

LOCATION OF NEGATIVE UNKNOWN

PHOTOGRAPH # 5 OF 9

MAY 23 1979

JUN 18 1979



Douglas

U.S. Post Office Co.

FEDERAL OFFICE BUILDING ROSEBURG, OREGON

1917 POST OFFICE LOBBY LOOKING EAST

PHOTOGRAPHER UNKNOWN

JUN 18 1979

LOCATION OF NEGATIVE UNKNOWN

MAY 23 1979

PHOTOGRAPH # 6 OF 9

#6



384-4

WHEN REORDERING - CALL FOR NO.....
THE PHOTO-LAB STUDIO
627 S. E. JACKSON
ROSEBURG, OREGON

U.S. Post Office Douglas Co.

FEDERAL OFFICE BUILDING ROSEBURG, OREGON

8/8/59 AERIAL VIEW SHOWING BLAST CRATER

PHOTO-LAB STUDIO

MAY 23 1979

627 S.E. JACKSON, ROSEBURG, OREGON

PHOTOGRAPH # 7 OF 9

MAY 18 1979



U.S. Post Office

Douglas
COI

FEDERAL OFFICE BUILDING ROSEBURG, OREGON

MARBLE STAIRCASE IN LOBBY LOOKING WEST

KRISTINE BAK, OPERATIONAL PLANNING STAFF 6/78

GSA REGIONAL HEADQUARTERS, REGION 10

PHOTOGRAPH # 8 OF 9

JUN 18 1979
MAY 23 1979



Douglas
U.S. Post Office County

FEDERAL OFFICE BUILDING ROSEBURG, OREGON

LAMP STAND ON CHEEK BLOCK AT MAIN ENTRANCE

KRISTINE BAK, OPERATIONAL PLANNING STAFF 6/78

GSA REGIONAL HEADQUARTERS, REGION 10 JUN 18 1979

PHOTOGRAPH # 9 OF 9

MAY 23 1979