



1 of 8

St. Francis Street Methodist Ch.

251 St. Francis Street

Robin Lang, Photographer

11/1982

MHDC negative files

North & East elevations

camera facing southwest



2 of 8

St. Francis Street Methodist Ch.

251 St. Francis Street

Robin A. Lang, Photographer

11/1982

MHDC negative files

North elevation

camera facing south



3 of 8

St. Francis Street Methodist Church

251 St. Francis Street

Robin A. Lang, Photographer

11/1982

MHDC negative files

main staircase

camera facing southeast



4 of 8

St. Francis Street Methodist Church

251 St. Francis Street

Robin A. Lang, Photographer

11/1982

MHDC negative files

Sanctuary

camera facing west



5 of 8

St. Francis Street Methodist Church

251 St. Francis Street

Robin A. Lang, Photographer

11/1982

MHDC negative files

detail of brackets

camera facing northeast



FROM LEE FINE CRIBB
111 W. 11th St. N. W.
MINNAPOLIS, MINN.
1911
MADE IN U.S.A.
RELIABLE STAINED GLASS

6 of 8

St. Francis Street Methodist Church

251 St. Francis Street

Robin A. Lang, Photographer

11/1982

MHDC negative files

North stained glass window

camera facing north



7 of 8

St. Francis Street Methodist Church

251 St. Francis Street

Robin A. Lang, Photographer

11/1982

MHDC negative files

balcony

camera facing east



8 of 8

St. Francis Street Methodist Church

251 St. Francis Street

Robin A. Lang, Photographer

11/1982

MHDC negative files

typical door

camera facing east