



80-#-16

co.
Clementwood - Rutland, Vermont

Credit: Hugh H. Henry

Date: April 1980

AUG 4 1980

Negative filed at Vermont Division for
Historic Preservation

Description: Clementwood (#1) - east and
north elevations. View looking SW.

Photograph 1 / 4

SEP 27 1980



80-#-16

CO1

Clementwood - Rutland, Vermont

Credit: Hugh H. Henry

AUG 4 1980

Date: April 1980

Negative filed at Vermont Division for
Historic Preservation

SEP 27 1980

Description: Clementwood (#1) - N facade; ex-
caretaker's house (#4) to left. View looking S.

Photograph 2/4



80-7-16

^{cd.}
Clementwood - Rutland, Vermont

Credit: Hugh H. Henry

AUG 4 1980

Date: April 1980

Negative filed at Vermont Division for
Historic Preservation

Description: Ex-carriage barn (#2) - east and
north elevations. View looking SW.

Photograph 3/4

SEP 27 1980



80-A-16

cd.
Clementwood - Rutland, Vermont

Credit: Hugh H. Henry

Date: April 1980

AUG 4 1980

Negative filed at Vermont Division for
Historic Preservation

Description: E grounds of Clementwood. View
looking NE toward Green Mountains.

Photograph 4 *14*

SEP 27 1980