



TOWN OF
FRANKLIN
Municipal Office
JAN 11 1914
POLICE

PENNINGTON
COUNTY
LIBRARY

Property name: McCoy Home

Location: Franklin, WV 26807

DEC 10 1981

NOV 10 1981

Photo credit: Mr. David Hubbs, Franklin

Date of photo: August 15, 1981

Negative filed at: Dept. of Culture & Historic Preservation Unit, the Cultural Center, Capitol Complex, Charleston, WV 25301

Description of photo: Full frontal view of McCoy Home, Franklin, showing two of the three chimneys. These two were used primarily for heating. Guests were quartered in the two upper level rooms on the extreme right and left. Center window gives light to the upper landing. Lower right window was for parlor, lower left was the sitting room.

Direction of photo: West side of home.

1 of 4



Property name: McCoy Home
Location: Franklin, WV 26807

DEC 10 1981

NOV 10 1981

Photo credit: Mr. David Hubbs, Franklin
Date of photo: August 15, 1981

Negative filed at: Dept. of Culture & History
Historic Preservation Unit, The Cultural Center
Capitol Complex, Charleston, WV 25305

Description of photo: Side view of McCoy Home
showing windows for: on upper level, left to
right, guest room, nursery, and master bedroom;
on second level; parlor, dining room and pantry;
on lower level, the kitchen windows.

Direction of photo: South side of home.

2 of 4



Property Name: McCoy Home
Location: Franklin, WV 26807

DEC 10 1981

NOV 10 1981

Photo credit: Mr. David Hubbs, Franklin

Date of photo: August 15, 1981

Negative filed at: Dept. of Culture & History,
Historic Preservation Unit, The Cultural Center
Capitol Complex, Charleston, WV 25305

Description of photo: Side view of McCoy Home
showing triple level porch with stairs between and
and to the three lavatories.

Direction of photo: North side of home.

3 of 4



Property name: McCoy Home

Location: Franklin, WV 26807

DEC 10 1981

NOV 10 1981

Photo credit: Mr. David Hubbs, Franklin

Date of photo: August 15, 1981

Negative filed at: Dept. of Culture & Historical
Preservation Unit, The Cultural
Center, Capitol Complex, Charleston, WV 25301

Description of photo: Frontal view of
black servants' quarters. Notice chimney from
fireplace used for heating and cooking.

Building contains two rooms, one upper and

one lower.
Direction of photo: West side of servants'
quarters.

4 of 4