



Name: Eratt House

Location: Near Bridgeville, Sussex County, DE

Photographer: Richard B. Carter

Date: Dec., 1981

Location of Negative: Hall of Records, Dover, DE

Description: Facade view of the Eratt House

Photograph Number: 1 of 7



Name: Eratt House

Location: Near Bridgeville, Sussex County, DE


Photographer: Richard B. Carter

Date: Dec., 1981

Location of Negative: Hall of Records, Dover, DE

Description: View of south side of house showing conversion of first floor to a garage, and rear frame wing.

Photograph Numbers: 2 of 7



Name: Eratt House

Location: Near Bridgeville, Sussex County, DE'

Photographer: Richard B. Carter

Date: Dec., 1981

Location of Negative: Hall of Records, Dover, DE

Description: View of south side of house
showing details of major
alteration to house and details

Photograph Number: of brickwork.
3 of 7



10 GT. 31100

Fab

Name: Eratt House

Location: Near Bridgeville, Sussex County, DE

Photographer: Richard B. Carter

Date: Dec., 1981

Location of Negative: Hall of REcords, Dover, DE

Description: View of rear of house under
wooden shed addition, showing
two rear doorways.

Photograph Numbers

4 of 7



Name: Eratt House

Location: Near Bridgeville, Sussex County, DE

Photographer: Richard B. Carter

Date: Dec., 1981

Location of Negatives: Hall of Records, Dover, De

Description: View of first floor interior of house showing what was once the parlor (with grease pit in bottom foreground).

Photograph Numbers 5 of 7



Eratt House

Name:

Location: Near Bridgeville, Sussex County, DE

Photographer: Richard B. Carter

Date: Dec., 1981

Location of Negative: Hall of Records, Dover, DE

Description: View of diagonal fireplace in
parlor (from which original
paneling has been removed).

Photograph Numbers

6 of 7



Name: Eratt House
Near Bridgeville, Sussex County, DE
Location:
Photographer: Richard B. Carter
Date: Dec., 1981
Location of Negative: Hall of Records, Dover, DE

Description: Detail view of second floor interior showing window, plank partition wall, and exposed beam ceiling.

Photograph Numbers

7 of 7