



Fabric Fire Hose Co.

Newtown, CT

D. Ransom Photo, 9/81

Negative: Connecticut

Historical Commission

DAM, VIEW SOUTH

Photograph 1 of 9



Fabric Fire Hose Co.

Newtown, CT

D. Ransom Photo, 9/81


Negative: Connecticut

Historical Commission

VIEW NORTH

Photograph 2 of 9

2



Fabric Fire Hose Co.

Newtown, CT

D. Ransom Photo, 9/81

Negative: Connecticut

Historical Commission

TOWER, VIEW NORTHWEST

Photograph 3 of 9



Fabric Fire Hose Co.

Newtown, CT

D. Ransom Photo, 9/81

Negative: Connecticut
Historical Commission

ENTRANCE, VIEW

NORTHEAST

Photograph 4 of 9



Fabric Fire Hose Co.

Newtown, CT

D. Ransom Photo, 9/81

Negative: Connecticut

Historical Commission

VIEW SOUTHWEST

Photograph 5 of 9



Fabric Fire Hose Co.

Newtown, CT


D. Ransom Photo, 9/81

Negative: Connecticut
Historical Commission

POSTS, SECOND FLOOR,

VIEW NORTHWEST

Photograph 6 of 9



Fabric Fire Hose Co.

Newtown, CT

D. Ransom Photo, 9/81

Negative: Connecticut

Historical Commission

ROOF TRUSS

Photograph 7 of 9



Fabric Fire Hose Co.

Newtown, CT

D. Ransom Photo, 9/81

Negative: Connecticut

Historical Commission

FOURTH FLOOR, VIEW

NORTHWEST

Photograph 8 of 9



Fabric Fire Hose Co.

Newtown, CT

D. Ransom Photo, 9/81

Negative: Connecticut
Historical Commission

END OF LINE SHAFT,

VIEW SOUTH

Photograph 9 of 9