## **Utah State Historical Society**

## Historic Preservation Research Office

Site No. <u>BV-04-151</u> Sign. Site 24

## Structure/Site Information Form

	Street Address: 90 N. 2nd We	oat		IJT	M 1	2/356250/42	27350	
	90 N. Zhd west				1.			
	Name of Structure:			T.		R.	S.	
	Present Owner: Kathleen S. Farnsworth			Les	ss th	an one Acre	<u>,</u> '	
	Owner Address: Beaver, Utah 84713							
	Year Built (Tax Record): Legal Description			re Age: T Building:		Tax#: <sub>B-99</sub>		
	Plat A Blk 27 Lot 3							
	Original Owner: Reeves, Sylvester H., House Construction Date: c. 1885 Demolition Date:							
	keeves, Syr	vester m., r.	Loube					
	neeves, by	vester n., r						
	Original Use: residence	vester II., I	Present Use		mily			
	Original Use: residence	egrity:		e: single-fa	-	al Register St	atus:	
	Original Use: residence  Building Condition: Inte		Pres⊖nt Use	e: single-fa	Fina	al Register St	atus: □ District	
	Original Use: residence  Building Condition: Inte	egrity:	Present Use Preliminary Eva	e: single-fan	Fina	•		
	Original Use: residence  Building Condition: Inte	egrity: Inaltered	Present Use Preliminary Eva	e: single-fan	Fina	ational Landmark	☐ District	
	Original Use: residence  Building Condition: Inte	egrity: Inaltered Minor Alterations	Present Use Preliminary Eva  ☐ Significant ☐ Contributory	e: single-fan	Fina	ational Landmark ational Register	☐ District	
	Original Use: residence  Building Condition: Inte	egrity: Inaltered Minor Alterations Major Alterations	Present Use  Preliminary Eva  Significant Contributory Not Contributory  Slide No.:	e: single-faral	Fina  N N S Ographs:	ational Landmark ational Register tate Register	☐ District ☐ Multi-Resourc ☐ Thematic	
-	Original Use: residence  Building Condition: Inte	egrity: Inaltered Minor Alterations Major Alterations	Present Use  Preliminary Eva  Significant Contributory Not Contributory  Slide No.:	single-faralluation:  Not of the Historic Period  Date of Photo	Fina  N N S Ographs:	ational Landmark ational Register tate Register	☐ District ☐ Multi-Resourc ☐ Thematic	
	Original Use: residence  Building Condition: Inter  Excellent Site JU Good Ruins M Deteriorated X Photography: Date of Slides:  Views: X Front Side	egrity: Inaltered Minor Alterations Major Alterations	Present Use  Preliminary Eva  Significant Contributory Not Contributory  Slide No.:	single-faralluation:  Not of the Historic Period  Date of Photo	Fina  N  S  Regraphs:	ational Landmark ational Register tate Register	☐ District ☐ Multi-Resourc ☐ Thematic	
	Original Use: residence  Building Condition: Inter  Excellent Site JU  Good Ruins M  Deteriorated X M  Photography: Date of Slides:  Views: X Front Side  Research Sources:	egrity:  Inaltered Minor Alterations Major Alterations  Program Control  Rear Cother	Present Use  Preliminary Eva  Significant Contributory Not Contributory  Slide No.:	Single-faraluation:  Not of the Historic Period  Date of Photo	Fina  N N S Ographs:	ational Landmark ational Register tate Register	☐ District ☐ Multi-Resourc ☐ Thematic	
	Original Use: residence  Building Condition: Inter  Excellent Site JU  Good Ruins M  Deteriorated X M  Photography: Date of Slides:  Views: X Front Side  Research Sources: Abstract of Title Sanborn Mag	egrity:  Inaltered  Minor Alterations  Major Alterations  E	Present Use  Preliminary Eva  Significant Contributory Not Contributory Slide No.: Vie	Single-faralluation:  Not of the Historic Period  Date of Photo	Fin:  N N S Ographs:  Helicological Properties of the properties o	ational Landmark ational Register tate Register ar   Other	☐ District ☐ Multi-Resourc ☐ Thematic	
-	Original Use: residence  Building Condition: Interpretation	egrity:  Inaltered  Inior Alterations  Major Alterations  Rear Other  ps  ries  I Encyclopedias	Present Use  Preliminary Eva  Significant Contributory Not Contributory  Slide No.:  Vie	Single-far	Final N N N N S S S S S S S S S S S S S S S	ational Landmark ational Register tate Register ar □ Other U Library	☐ District ☐ Multi-Resourc ☐ Thematic  Photo No.:	

1933 photo on tax records

Mrs. Kathleen Farnsworth interviewed August, 1976 and September 1977 in Beaver, by L. L. Bonar

Researcher: Linda L. Bonar

Date: 9/21/78

Street Address: 90 North 2nd West c. 1885

Site No:

Architect/Builder:

not known, perhaps Sylvester Reeves

**Building Materials:** 

Pink (tuff) rock

Building Type/Style:

Crosswing/ greek revival

Description of physical appearance & significant architectural features: (Include additions, alterations, ancillary structures, and landscaping if applicable)

The Sylvester Reeves House is a 1 1/2 story pink tuff stone structure (now painted white), built about 1885. A crosswing house plan, this house has an unusual configeration with a shed extension on the end and back side of the wing. The moderately pitched gable roof has a boxed cornice with a frieze, and gable returns. Decorative elements are provided by the cornice, a bay window, a porch, and two corbelled chimney caps. The house is distinguished by its stone construction and unusual configuration. In excellent condition, it has no major alterations. The white paint obscures the original color of the house, but is not considered here a significant alteration. A stone outbuilding is also included in the nomination.

The forward projecting gable end of this crosswing house has a projecting bay the height of the cornice line. The bay has one-over-one double-hung windows, two on the front and one on each side. The crosswing is long and is pierced by a door and two windows. The two-over-two windows have wooden architrave trim. A low hip porch spans the crosswing and wraps around the side where there is a door. This side, it is almost as if the end gable was split and the rear of the gable was projected out further to the side, enought to accomodate another door on the front of the extension. The same cornice as the main house continues over this extension which was built as part of the

Statement of Historical Significance:

Construction Date:

The Sylvester Reeves house, built c. 1885 is significant as one of 13 examples of the crosswing house type, one of the principal dwelling types found in Beaver during the late 19th century. The 1 1/2 to 2 story crosswing house largely replaced the "I" house as an architectural symbol of economic and social status in Utah during this period, though in Beaver the older "I" house form continued as a viable middle-class dwelling until the turn-of-the-century. The Reeves house is one of the best crosswing examples to survive in Beaver and makes an important contribution to the town's historic landscape. The stone wash house/granary is significant because it is one of few surviving intact outbuildings in the town.

HISTORY 5

Reeves, Sylvester H., Hosue Continuation of section 4

original house. The porch has elaborate jigsaw cut posts and brackets.

The stone granary/washhouse is rectangular and has two large rooms. The gable roof has a simple boxed cornice with a frieze and is capped by two corbelled chimneys. Three deeply set entries pierce the broadside of the structure.