

Plant Engineering Office, Ford Motor Company, at intervals of two or three years, has an extensive series of aerul photographs taken, of the Rouge Complex and other major buildings. These become part of the Company's permanent seends. This was taken in 1975.



Photo No. 2
By: Ralph J. Christian, AASLH
Negative at: Historic Sites Survey
Date: February, 1977

View: From south, showing south end of Dearborn Assembly Plant (Building B).



Photo No. 3 Courtesy: Ford Motor Company

View: Automobile assembly process in Dearborn Assembly Plant (Building B) circa 1973.



Photo No. 4 Courtesy: Ford Motor Company

View: Automobile assembly line in Dearborn Assembly Plant (Building B) circa 1973.



Photo No. 5
By: Ralph J. Christian, AASLH
Negative at: Historic Sites Survey
Date: February, 1977

View: From west, showing portion of west facade of Glass Plant.



Photo No. 6
By: Ralph J. Christian, AASLH
Negative at: Historic Sites Survey
Date: February, 1977

View: From east, showing east facade of Power House.



Photo No. 7
By: Ralph J. Christian, AASLH
Negative at: Historic Sites Survey
Date: February, 1977

View: From east, showing facade of Henry Ford II Blast Furnace (Blast Furnace A).



Photo No. 8
By: Ralph J. Christian, AASLH
Negative at: Historic Sites Survey
Date: February, 1977

View: From east, showing east facade of Dearborn Iron Foundry.



Photo No. 9
By: Ralph J. Christian, AASLH
Negative at: Historic Sites Survey
Date: February, 1977

View: From east, showing portion of east facade of Steel Mill Plant.