### **United States Department of the Interior** National Park Service

JAN 2 7 1989

# National Register of Historic Places Registration Form

NATIONAL REGISTER

This form is for use in nominating or requesting determinations of eligibility for individual properties or districts. See instructions in *Guidelines* for Completing National Register Forms (National Register Bulletin 16). Complete each item by marking "x" in the appropriate box or by entering the requested information. If an item does not apply to the property being documented, enter "N/A" for "not applicable." For functions, styles, materials, and areas of significance, enter only the categories and subcategories listed in the instructions. For additional space use continuation sheets (Form 10-900a). Type all entries.

(Form 10-900a).	Type all entries.	,	•					•	
1. Name of F	Property		·						<u> </u>
historic name		Mohle,	Wilh	elmina,	House				
other names/sit	te number	N/A							
2. Location									
street & number	)r	734 S.E	. 34th					not for publication	
city, town		Portlar	ıd					vicinity	
	regon	code	OR	county	Multnomah	code	051	zip code	97214
3. Classificat	tion			· · · · · · · · · · · · · · · · · · ·					
Ownership of P	roperty		Category	of Property		Number of F	Resou	rces within Property	
x private			🔀 buildi			Contributing		Noncontributing	
public-local	•		distric	• • •		1		buildings	
public-State			site	•				sites	
public-Fede			struct	tur <b>a</b>				structures	
basiic-r-ede	101		Objec			<del></del>			
			oplec	•			•	objects Total	
Name of relate		erty listing ctural. R	: lesourc	es				outing resources previnal Register N/A	•
of Eastside 4. State/Fede		Certificat	ion			<del></del>			
	certifying official	· · · · · · · · · · · · · · · · · · ·		Wy V	c Preservat			ontinuation sheet.  January 23, Date	<u>1989</u>
State or Fede	ral agency and b		ni Stat	e mscyr.	C FIESELVAL.	ION OTTICE			
In my opinio	n, the property	meets	does	not meet the	e National Regist	ter criteria.	See co	ontinuation sheet.	
Signature of c	commenting or ot	her official						Date	
State or Fede	ral agency and b	ureau					,		
5. National P	Park Service (	Certificat	ion				-		
I, hereby, certif					0				1
	he National Re	•		Silver	u Bolin	Entered No. 44	in ±	ha 3/4	1/19
See conti	inuation sheet.		س_)	/ purch	10/	Mational	Rag	1010	/ /
determined	eligible for the	National			v			.co 29th	
Register.	See continuation	on sheet.							
determined	not eligible for	the							
. National Re	•								
	g.0.0.				····	· · · · · · · · · · · · · · · · · · ·			
removed fro		Register.	-		<del> </del>	N-1			
removed from the contract of t	om the National	Register.							
	om the National	Register.		· · · · · · · · · · · · · · · · · · ·	VSignature of the			Date of Act	

6. Function or Use				
Historic Functions (enter categories from instructions)  DOMESTIC; Single Dwelling	Current Functions (enter categories from instructions) DOMESTIC; Single Dwelling			
7. Description				
Architectural Classification enter categories from instructions)	Materials (ente	er categories from instructions)		
	foundation	Brick		
Queen Anne	walls	Weatherboard		
		Shingle		
	roof	Asphalt		
	other	Wood		
	<del> </del>			

Describe present and historic physical appearance.

#### EXTERIOR DESCRIPTION

This corner lot is surrounded by a concrete retaining wall three-feet high and has no original outbuildings associated with it. Asymmetrical in plan, this two-and-one-half story house is built on a brick foundation with a full basement. The roof line, presently of composition shingles, has many sections to it. Primarily a hip roof, three cross intersecting gables project out over two-story polygonal window bays which have bracketed hoods of jigsawn tracery and pendants ornamenting them. A partial wrap-around front porch on the northwestern corner has a flat roof which is lined by an enclosed, shingled balustrade. Another attached porch to the rear of the northeastern corner has a shed roof supported by slender turned columns. Two chimneys rise from the roof; one in the center of the structure, the other at the eastern end. One shed dormer projects from the eastern hipped end.

The exterior is covered with a variety of siding types which give a multitextured appearance to the structure. At the bottom of the first floor, below the windows, are recessed panels of wide, tongue-and-groove. The first floor and ground floor siding is bevel-channelled shiplap. At the top of the first floor is a fascia board of recessed panels with a diagonal raised pattern and semi-circle patterns over the window openings.

The semi-circle patterns are bordered by sunburst-like spandrels. A two-foot wide band of imbricated shingles separates the first floor from the second. Employed in this shingled course are hexagonal, rectangular and fishscale patterns. At the top of the second floor, another band of ornamental panelled frieze with wooden lattice work provides embellishment below the cornice. In the gabled ends, small palladian windows pierce the wall and have sunburst ornamentation on either side of the central arch. Patterned shingles fill the rest of the gable ends. The windows on the first two levels are predominantly narrow one-over-one double-hung sash, as well as some large single panes bounded by small squares of multi-colored glass.

### United States Department of the Interior National Park Service

# National Register of Historic Places Continuation Sheet

Section	number	7	Page	2
0000001			raye	~

The original front doors with etched glass transom lights and surrounding setin molded panels are extant. Part of the beaded spindlework frieze further embellished by scroll-cut braces exists, but the complimentary balustrade has been removed for restoration.

The building is almost completely intact except for two new windows which were installed on the dining room in 1929. A 1923 integrated basement-level garage in the south side of the house was added in 1923.

#### INTERIOR DESCRIPTION

Asymmetrical in plan, tall, narrow rooms, with irregular polygonal shapes, characterize the interior of the house.

Entry is gained by paired, panelled and glazed doors, with a hexagonal transom light. The light is etched with a deer scene surrounded by cattails and other flora. The foyer is richly decorated. Finishwork consists of dark, stained baseboard with crown molding, molded door and window frames, each with cannonball motif corner pieces. The graceful staircase with turned balusters rises from two platform steps before turning ninety degrees, rising nine steps, then curving six more steps to the second floor landing. The combed and chamfered newel post has a raised panel embellished with a floral motif and a turned spherical cap.

The parlor is entered from the hall through tall pocket doors. Built-in bookcases, which appear to be a twentieth-century addition, are located opposite the hall pocket doors. The room has polygonal bay windows below which are diagonal panels.

The same panelled treatment has been used on the bay windows in the sitting room. This room has a handsome green marble fireplace. The ceramic hearth is composed of two types of tiles: cordovan-red rectangular and triangular tiles, and raised floral motif tiles. There is a large, circular ceiling flange and light fixture in the sitting room, as well as in the parlor. A set of pocket doors separate the sitting room and the parlor.

## United States Department of the Interior National Park Service

## National Register of Historic Places Continuation Sheet

Section	number	7	Page	3
			3-	

A back hall, stairs and bath divide the front from the back of the house. The stairs have a newel post with a large turned shaft, square base and half-sphere cap. The balusters are also turned. The bath has bevelled tongue-and-groove wainscoting, a built-in tub, wall-hung sink, toilet and ceiling light fixture.

The kitchen and dining room are off the back hall. Each has a ceiling light fixture. The dining room has a built-in buffet with glass doors, drawers, and a minor wall above the countertop. The dining room has plain surrounds unlike the front rooms off the first floor.

The upstairs is arranged along a long, central hallway. The floors are fir with plain baseboards. The vertical panelled doors have operable transom lights. At one time, the home was used as a duplex. A kitchen had been carved out of a bedroom. That room is now used as a laundry room. A full bathroom with clawfoot tub is adjacent to the present laundry room. Mock brick linoleum is applied to the bathroom wall below a chair rail.

The bedrooms above the parlor and sitting room have polygonal bay windows with combed panels below the sills. Two of the bedrooms have closets with built-in drawers as does the closet off the central hall.

9 Statement of Significance	
8. Statement of Significance  Certifying official has considered the significance of this property in nationally state	relation to other properties:  ewide
Applicable National Register Criteria A B C D	
Criteria Considerations (Exceptions)	D E F G
Areas of Significance (enter categories from instructions)  Architecture	Period of Significance Significant Dates 1890 1890
	Cultural Affiliation N/A
Significant Person N/A	Architect/Builder Unknown

State significance of property, and justify criteria, criteria considerations, and areas and periods of significance noted above.

This house is locally significant under criterion C as a well-preserved, excellent representative of a Victorian period dwelling incorporating elements of both the Queen Anne and Stick styles. Constructed about 1890, it was built in the heyday of the Queen Anne style's popularity. The date of construction is based on Sanborn Insurance maps: the building is not shown on the 1888 map but does appear on the 1890 map.

This property is one of 27 single-family houses included in the survey which is designed in the Queen Anne style. The houses range in date from 1883 to 1909, with over 75 percent built at the same approximate time as the subject house.

This large residence exhibits the asymmetrical massing and decorative features characteristic of Queen Anne architecture. It is distinctive among the surveyed properties because of the variety of siding materials which includes horizontal tongue and groove, shiplap, and imbricated shingles—hexagonal, rectangular, and fishscale. Also of interest are the paneled courses, each with distinctive decorative patterns, which wrap around the building at various levels. The basket-weave pattern found at the eaveline course and the diagonally applied dowels at the head of the first floor windows are unique in the study area. The bowed, recessed porch is not found anywhere else in the study area. The entrance is also unique and the paired, paneled—and—glazed doors are articulated by a hexagonal transom with etched glass.

The interior is richly decorated throughout; however, the most distinctive element is the handsome green marble fireplace in the sitting room.

## United States Department of the Interior National Park Service

### National Register of Historic Places Continuation Sheet

Section	number	8	Page	2

Deed records indicate the original owner of the house was Wilhelmina Mohle who purchased the property from the Sunnyside Land and Improvement Company in 1889. Records are unclear as to how long she owned it. The next recorded title transaction is in 1907 when Louise and John Boldt sold the house to Frank M. Fliter in whose family it remained until approximately 1929.

Although there is no conclusive evidence to document the fact, it is quite likely that the house was constructed by local contractor John Wallace, who is known to have built many of Sunnyside's early buildings.

9. Major Bibliogr	aphical References		
. City of Port	tland Building Bureau microform	and card files.	
. City of Port	tland Bureau of Planning, Portla	nd Historic Resour	ce Inventory, 1983.
. Multnomah Co	ounty Tax Assessor records, micr	oform, and card fi	les, Portland, 1980.
. Polk, R. L.	and Co., Portland City Director	ies, 1895-1900.	
. Ticor Title	Company records, Portland, Oreg	on.	
. Phelps, Lind	da (tenant). Unrecorded intervie	w by Jane Morrison	, July 1988.
		See continuatio	on sheet
has been reques previously listed previously deterr designated a Na recorded by Hist Survey # recorded by Hist	rmination of individual listing (36 CFR 67)	Primary location of  State historic processes Other State age Federal agency Local governme University Other Specify repository:	reservation office ency
10. Geographical			
Acreage of property	Less than one acre Portla	<u>nd. Washington-Ore</u>	gon 1:6250
UTM References A 1 10 5 2 9 Zone Easting C 1	0.7.5 5.0 4.0 2.5.0 Northing	B Zone Easting D See continuatio	Northing  In sheet
Wash at Day and an Day			
Verbal Boundary De	e addition & Plat 2 & 3, Lot 1 &	_	•
		See continuatio	n sheet
Boundary Justification	20		
Dodnadi, odomodii			
Taxlot li	nes		
		See continuatio	n sheet
11. Form Prepare	ed By		
name/title	K. Zisman, J. Koler, J. Morri		
organization			August 15, 1988
street & number		telephone	(503) 234-4801 Oregon zip code 97214
city or town	Portland	state	Oregon zip code 97214

