

SPEED
LIMIT
35



1. Cavalry Cottage
2. Ocean County, NJ
7. Photograph 1 of 32



1. Cavalry Cottage
2. Ocean County, NJ
7. Photograph 2 of 32



1. Cavalry Cottage
2. Ocean County, NJ
7. Photograph 3 of 32



1. Cavalry Cottage
2. Ocean County, NJ
7. Photograph 4 of 32



1. Cavalry Cottage
2. Ocean County, NJ
7. Photograph 5 of 32



1. Cavalry Cottage
2. Ocean County, NJ
7. Photographs 6 of 32




1. Cavalry Cottage
2. Ocean County, NJ
7. Photograph 7 of 32



1. Cavalry Cottage
 2. Ocean County, NJ
7. Photograph 8 of 32

Wing 1 →
Wing 2 →
Wing 3 →
Wing 4 ↓



1. Caudry Cottage
2. Ocean County, NJ
7. Photograph 9 of 32



RELOC.
Paint
L.S.S.
LAYERS
○

1. Cavalry Cottage
2. Ocean County, NJ
7. Photograph 10 of 32



later

Earlier hinges

both
levels of
wood
refer
to
panels

1411

Washington Institute

1. Cavalry Cottage
2. Ocean County, NJ
7. Photograph 11 of 32

1. Cavalry Cottage
2. Ocean County, NJ
7. Photograph 12 of 32

original location of the Top board



original door was taller



Door is not original
that door is made by 184c

original track

Evidence of the original hinge

original hinge

piece of the original lock

original holes of nails



1. Cavalry Cottage
2. Ocean County, NJ
7. Photograph 13 of 32



1. Cavalry Cottage
2. Ocean County, NJ
7. Photograph 14 of 32



Chimney

Fireplaces
shift

1. Cavalry Cottage
2. Ocean County, NJ
7. Photograph 15 of 32

Top of the
original
door

hinge of the
original
door



1. Cavalry Cottage
2. Ocean County, NJ
7. Photograph 16 of 32



1. Cavalry Cottage
2. Ocean County, NJ
7. Photograph 17 of 32



1. Cavalry Cottage
2. Ocean County, NJ
7. Photograph 18 of 32



1. Cavalry Cottage
2. Ocean County, NJ
7. Photograph 19 of 32



1. Cavalry Cottage
2. Ocean County, NJ
7. Photograph 20 of 32



1. Cavalry Cottage
2. Ocean County, NJ
7. Photograph 21 of 32

stair is not
original one
This is not the
original location

Finished by
TRIM of P
very original
door is the
of the stair



1. Cavalry Cottage

2. Ocean County, NJ

7. Photograph 22 of 32



1. Cavalry Cottage
2. Ocean County, NJ
7. Photograph 23 of 32



1. Cavalry Cottage
2. Ocean County, NJ
7. Photograph ~~24~~ of 32



1. Cavalry Cottage
2. Ocean County, NJ
7. Photograph 25 of 32



1. Cavalry Cottage
2. Ocean County, NJ
7. Photograph 26 of 32



1. Cavalry Cottage
2. Ocean County, NJ
7. Photograph 27 of 32




1. Cavalry Cottage
2. Ocean County, NJ
7. Photograph 28 of 32

late 1940s
dash

Winged
Wall →



1. Cavalry Cottage
2. Ocean County, NJ
7. Photograph 29 of 32

A black and white photograph of an interior wall. On the left, there is a window with a wooden frame and a white object on the sill. The wall is covered in a light-colored material, possibly plaster or lath. A horizontal line runs across the wall, with a small dark object on top of it. Below this line, there are two columns of handwritten text. The left column has an upward-pointing arrow above the text. The right column has an upward-pointing arrow above the text. The floor is dark and appears to be covered in debris.

↑ LATH &
PLASTER
ARE NOT
ORIGINAL

↑ THE MIDDLE
OF THE
WAS
WHITEWASHED

1. Cavalry Cottage
2. Ocean County, NJ
7. Photograph 30 of 32



↑ LATH &
PLASTER
ARE NOT
ORIGINAL

1. Cavalry Cottage
2. Ocean County, NJ
7. Photograph 31 of 32



1. Cavalry Cottage

2. Ocean County, NJ

7. Photograph 32 of 32