

Pioneer Building, 1890 Pioneer Square Seattle. Washington N.P.S. Photo, 1966 By CWISNEY






Main entrance, west side Pioneer Building. 02/14/ 77. If reproduced, credit John W. Snyder.



Interior, Pioneer Building View up light well to sky-light. 02/14/77. If reproduced, credit John W. Snyder.



Interior, Pioneer Building, View down light well from sixth level. If reproduced, credit John W. Snyder.



Interior, Pioneer Building View up light well from second level. 02/14/77. If reproduced, credit John W. Snyder.



Interior, Pioneer Building, View on 6th level, showing oak paneling, skylight, ornamental railing & columns. 02/14/77. If reproduced, credit John W. Snyder.



Main entrance foyer, Pioneer Building. 02/14/77. If reproduced, credit John W. Snyder.





Interior, Pioneer Building, Second level landing in foreground. If reproduced, credit John W. Snyder. 02/14/77.



Chief Seattle Fountain, 02/14/77. If reproduced, credit John W. Snyder.



Pioneer Square, Pergola, Pioneer Building, 02/14/77. If reproduced, credit John W. Snyder



Pioneer Square Pergola, view southwest. 02/14/77. If reproduced, credit John W. Snyder.



Pioneer Square Pergola. 02/14/77. If reproduced, credit John W. Snyder.



Ornamental column for ventilation of underground restroom. Pergola & Pioneer Building in background. 02/14/77. If reproduced, credit John W. Snyder.



Pioneer Square Pergola, detail. 02/14/77. If reproduced, credit John W. Snyder.



Pioneer Square Totem Pole. If reproduced, credit Seattle Office of Urban Conservation.



Pioneer Square Pergola, circa 1910. Pioneer Building in left background. If reproduced, credit Seattle Engineering Department.