

Photographer: James R. Lockhart Negative filed: Georgia Dept. of Natural Resources

Date: April 1987

Description: (1 of 16): Main house, front

view, photographer facing northwest.



- Photographer: James R. Lockhart
- Negative filed: Georgia Dept. of Natural
- Resources
- Date: April 1987
- Description: (2 of 16): Main House, front
- view, porch detail, photographer facing southwest.



Photographer: James R. Lockhart Negative filed: Georgia Dept. of Natural Resources Date: April 1987 Description: (3 of 16): Main House, second floor of porch, photographer facing northeast.



Photographer: James R. Lockhart Negative filed: Georgia Dept. of Natural Resources Date: April 1987 Description: (4 of 16): Main house, rear view showing covered walk adjacent to carport, photographer facing south.



Photographer: James R. Lockhart Negative filed: Georgia Dept. of Natural Resources Date: April 1987 Description: (5 of 16): Rear of Main House, with carport on left, well house in center and storage house on right, photo-grapher facing southeast.



Photographer: James R. Lockhart Negative filed: Georgia Dept. of Natural Resources

Date: April 1987

Description: (6 of 16): Outbuildings on southwest of Main House: Old wood shed,


old smokehouse, storage building, photographer facing northeast.



Photographer: James R. Lockhart Negative filed: Georgia Dept. of Natural Resources

Date: April 1987

Description: (7 of 16): Outbuildings as seen from southeast side of Main House; modern storage house on left & Old Cotton House on right, photographer facing northeast



Photographer: James R. Lockhart Negative filed: Georgia Dept. of Natural Resources Date: April 1987 Description: (8 of 16): Outbuilding on northeast side of Main House: Boiler Shed; Hog Gallows; and cane mill on right, photo-

grapher facing northwest.



Photographer: James R. Lockhart Negative filed: Georgia Dept. of Natural Resources

Date: April 1987

Description: (9 of 16): View of two outbuildings across road from Main House (taken from second floor of porch): Barn on left, shed on right, photographer facing east.



Photographer: James R. Lockhart Negative filed: Georgia Dept. of Natural Resources Date: April 1987 Description: (10 of 16): First floor, Main House: front door, entrance hall & stair landing, photographer facing southeast.



Photographer: James R. Lockhart Negative filed: Georgia Dept. of Natural Resources Date: April 1987 Description: (11 of 16): First floor, Main House: Master Bedroom (original living room) Mantel, photographer facing northeast.



Photographer: James R. Lockhart Negative filed: Georgia Dept. of Natural Resources Date: April 1987 Description: (12 of 16): First floor, Main house: Study mantel, photographer facing west.



Photographer: James R. Lockhart Negative filed: Georgia Dept. of Natural Resources Date: April 1987 Description: (13 of 16): First floor, Main house; Living room and Bay window, photographer facing east.



- Photographer: James R. Lockhart Negative filed: Georgia Dept. of Natural Resources Date: April 1987
- Description: (14 of 16): First floor,
- Main House: Formal Dining Room, photographer facing east.



Photographer: James R. Lockhart Negative filed: Georgia Dept. of Natural Resources Date: April 1987 Description: (15 of 16): Stairs between first and second floors, Main House, photographer facing southeast.



Photographer: James R. Lockhart Negative filed: Georgia Dept. of Natural Resources Date: April 1987 Description: (16 of 16): Second floor, Main House: Bedroom Number 4. photographer facing southeast.