




UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

**NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM**

(Type all entries - attach to or enclose with photograph)

1. NAME		
COMMON	AND/OR HISTORIC	NUMERIC CODE <i>(Assigned by NPS)</i>
American Security and Trust Company		JUL 16 1973
2. LOCATION		
STATE	COUNTY	TOWN
District of Columbia	District of Columbia	Washington
STREET AND NUMBER		
1501 Pennsylvania Avenue, NW		
3. PHOTO REFERENCE		
PHOTO CREDIT	DATE	NEGATIVE FILED AT
Wm. Edmund Barrett for NCPC	1973	NCPC
4. IDENTIFICATION		
DESCRIBE VIEW, DIRECTION, ETC.		

south Pennsylvania Avenue and east Fifteenth Street facades of American Security and Trust Company from the southeast. Riggs National Bank at the left.





UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM

(Type all entries - attach to or enclose with photograph)

1. NAME

COMMON American Security and Trust Company	AND/OR HISTORIC	NUMERIC CODE (Assigned by NPS) JUL 16 1973
--	-----------------	---

2. LOCATION

STATE District of Columbia	COUNTY District of Columbia	TOWN Washington
STREET AND NUMBER 1501 Pennsylvania Avenue, NW		

3. PHOTO REFERENCE

PHOTO CREDIT J. Alexander (copyright)	DATE 1964	NEGATIVE FILED AT National Capital Planning Commission
--	------------------	--

4. IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC.

East, 15th Street facade of American Security and Trust Company from
the northeast.

