

> UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY RECEIVED

DATE ENTERED

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

NAME

HISTORIC

The Reverend James McGready House AND/OR COMMON

Old Poorhouse

LOCATION

CITY, TOWN

NEGATIVE FILED AT

VICINITY OF Russellville

Russellville, Kentucky

Logan

STATE Kentucky

PHOTO REFERENCE

PHOTO CREDIT Martha Helen Smith, 540 South Main Street

DATE OF PHOTO February 14, 1976

COUNTY

same

IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET View from northeast showing rear ell of stone house at left. PHOTO NO.



> UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

RECEIVED DATE ENTERED

FOR NPS USE ONLY

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

NAME

HISTORIC

The Reverend James McGready House AND/OR COMMON

Old Poorhouse

LOCATION CITY, TOWN

Russellville

VICINITY OF

COUNTY Logan

STATE Kentucky

PHOTO NO 2 =

PHOTO REFERENCE

Commission

PHOTO CREDIT Bryan Cowherd, Kentucky Heritage

104 Bridge Street, Frankfort, Kentucky

DATE OF PHOTO 1975

IDENTIFICATION

NEGATIVE FILED AT

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

View from northwest. Ca. 1870 poorhouse wing is at right. Porch, second-story

gables, and eaves of stone house are later additions



> UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY RECEIVED DATE ENTERED

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS TYPE ALL ENTRIES -- IENCLOSE WITH PHOTOGRAPH

NAME

HISTORIC

Old Poorhouse

AND/OR COMMON

The Reverend James McGready House

LOCATION

CITY, TOWN

Russellville

VICINITY OF

COUNTY

STATE

Logan Kentucky

PHOTO REFERENCE

PHOTO CREDIT Martha Helen Smith

DATE OF PHOTO February 1976

NEGATIVE FILED AT 540 South Main Street, Russellville, Kentucky

IDENTIFICATION

DESCRIBE VIEW. DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

PHOTO NO

View from southeast. Rear ell of house at right; poorhouse wing at left; later additions in center. Note unique stone hood over basement entrance.



UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY

DATE ENTERED APR 9 1 1976

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS

TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC Old Poorhouse

AND/OR COMMON
The Reverend James McGready House

2 LOCATION

CITY, TOWN

Russellville

VICINITY OF

COUNTY Logan STATE Kentucky

3 PHOTO REFERENCE

РНОТО СПЕDIT Martha Helen Smith

DATE OF PHOTO February 1976

NEGATIVE FILED AT 540 South Main Street, Russellville, Kentucky

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

PHOTO NO. 4

Original mantel and chair-railing in second-story chamber. Note original split lath. Mantel has partially reeded band between shelf and frame of fireplace opening.



> UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY RECEIVED DATE ENTERED

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

NAME

HISTORIC Old Poorhouse

AND/OR COMMON The Reverend James McGready House

LOCATION

CITY, TOWN Russellville VICINITY OF

COUNTY Logan STATE Kentucky

PHOTO REFERENCE

PHOTO CREDIT Martha Helen Smith

February 1976 DATE OF PHOTO

NEGATIVE FILED AT 540 South Main Street, Russellville, Kentucky

IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

PHOTO NO. 5 View is burned-out second-story west chamber showing original chair-railing extending

into south dormer (window frame is not original). Roof of rear ell is at left.



> UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY RECEIVED APR 21 1976

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

NAME

HISTORIC

Old Poorhouse

AND/OR COMMON The Reverend James McGready House

LOCATION

CITY, TOWN

Russellville

VICINITY OF

COUNTY Logan

STATE

PHOTO NO.

Kentucky

PHOTO REFERENCE

Martha Helen Smith PHOTO CREDIT

DATE OF PHOTO February 1976

NEGATIVE FILED AT 540 South Main Street, Russellville, Kentucky

IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

Panelled window frame on east side of rear ell.



UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY

RECEIVED

MAR 2 2 1976

DATE ENTERED APR 2 1 1976

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS

TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

Old Poorhouse

AND/OR COMMON

The Reverend James McGready House

2 LOCATION

CITY, TOWN

___VICINITY OF

COUNTY

STATE

Logan Kentucky

Russellville

PHOTO REFERENCE

рното сперіт Martha Helen Smith

DATE OF PHOTO February 1976

NEGATIVE FILED AT 540 South Main Street, Russellville, Kentucky

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

PHOTO NO. 7

Stone lintel of original basement visible above modern porch floor. Lintel appears to be a single large stone scored to give illusion of jack arch with keystone.



UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY

RECEIVED MAR 2 2 1976

DATE ENTERED APR 2 1 1976

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS

TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC

Old Poorhouse

Russellville

AND/OR COMMON

The Reverend James McGready House

2 LOCATION

CITY, TOWN

___VICINITY OF

COUNTY Logan STATE Kentucky

PHOTO REFERENCE

PHOTO CREDIT Martha Helen Smith, 540 South Main Street, DATE OF PHOTO February 1976 Russellville, Kentucky

NEGATIVE FILED AT Same

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

PHOTO NO. 8

East window of rear ell. Again, lintel may be a single stone scored to suggest arch and keystone.



Form No. 10-301a (Rev. 10-74) UNITED STATES DEPARTMENT OF THE INTERIOR

STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY

RECEIVED: MAR 2 2 1976

DATE ENTERED APR 2 1 1976

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS

TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC

---

Old Poorhouse

The Reverend James McGready House

2 LOCATION

CITY, TOWN

Russellville

__VICINITY OF

Logan

STATE Kentucky

3 PHOTO REFERENCE

PHOTO CREDIT Martha Helen Smith, 540 South Main Street, DATE OF PHOTO February 1976
Russellville, Kentucky
NEGATIVE FILED AT Same

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

9

PHOTO NO

Fireplace opening in basement.



UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

RECEIVED MAR 2 2 1976

DATE ENTERED APR 2 1 1978

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC

Old Poorhouse

The Reverend James McGready House

2 LOCATION

AND/OR COMMON

CITY. TOWN

-VICINITY OF

Logan

COUNTY

STATE Kentucky

3 PHOTO REFERENCE

Russellville

PHOTO CREDIT Martha Helen Smith, 540 South Main Street, DATE OF PHOTO February 1976
Russellville, Kentucky
NEGATIVE FILED AT Same

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

РНОТО NO. 10

Hand-hewn floor joists in basement with mortised and pegged hearth support.



UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY

RECEIVED MAR 2 2 1976

DATE ENTERED APR 2 1 1976

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS

TYPE ALL ENTRIES -- ENCLOSE WITH PHOTOGRAPH

1 NAME

HISTORIC

Old Poorhouse

The Reverend James McGready House

2 LOCATION

CITY, TOWN

_VICINITY OF

COUNTY

STATE

Logan Kentucky

3 PHOTO REFERENCE

Russellville

РНОТО СВЕДІТ Bryan Cowherd, Kentucky Heritage Commission DATE OF PHOTO 1975

NEGATIVE FILED AT 104 Bridge Street, Frankfort, Kentucky

4 IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

рното NO. 11

Poorhouse wing from north.

RUSSELLVILLE Q KENTUCKY-L(F KENTUCKY 7.5 MINUTE SERIES (ISTRIAL DEVELOPMENT BOARD SW/4 RUSSELLVILLE 15 LEWISBURG 8.5 MI. EPLEYS 3.7 MI. 55 WISBURG) Sewage Disposal The Reverend James McGready House, Russellville, Logan County, Kentucky. Latitude 360 50' 14" Longitude 86⁰ 54' 52" (0)