




Property Name: Spring Banke  
Location: Clarksville, Delaware  
Photographer: Sue Fox  
Date: February 1976  
Location of Negative: Historic Pres. Section  
Div. of Hist. and Cult.  
Affairs  
Dover, Delaware  
Description: North facade  
Photograph Number: 1 *129*

APR 5 1976

*4/30/76*  
*Sussex County, Delaware*



Property Name: Spring Banke

Location: Clarksville, Delaware

Photographer: Sue Fox

Date: February 1976

Location of Negative: Historic Pres. Section  
Div. of Hist. and Cult.  
Affairs  
Dover, Delaware

Description: South facade

Photograph Number: 2 49

APR 5 1976

4/30/76

Sussex County, Delaware



Property Name: Spring Banke

Location: Clarksville, Delaware

Photographer: Sue Fox

Date: February 1976

Location of Negative: Historic Pres. Section  
Div. of Hist. and Cult.  
Affairs  
Dover, Delaware

Description: East end

Photograph Number: 3 49

APR 5 1976

4/30/76

Sussex County, Delaware



Property Name: Spring Banke

Location: Clarksville, Delaware

Photographer: Sue Fox

Date: February 1976

Location of Negative: Historic Pres. Section  
Div. of Hist. and Cult.  
Affairs  
Dover, Delaware

Description: West end and south facade

Photograph Number: 64 *of 9*

APR 5 1976

*4/30/76*

*Assess County, Delaware*





Property Name: Spring Banke  
Location: Clarksville, Delaware  
Photographer: Sue Fox  
Date: February 1976  
Location of Negative: Historic Preservation  
Section  
Division of Historical  
and Cultural Affairs  
Dover, Delaware


Description: South facade

Photograph Number: 5 *of 9*

APR 5 1976

*4/30/76*

*Sussex County, Delaware*





Property Name: Spring Banke

Location: Clarksville, Delaware

Photographer: Brent Clark

Date: February 1976

Location of Photograph: William Henry  
210 Pennsylvania Avenue  
Dover, Delaware

Description: Interior south wall of original  
section

Photograph number: 6 of 9

APR 5 1976

4/30/76

Sussex County, Delaware



Property Name: Spring Banke  
Location: Clarksville, Delaware

Photographer: Brent Clark  
Date: February 1976

Location of Negative: William Henry  
210 Pennsylvania Avenue  
Dover, Delaware

Description: Interior southeast corner of later  
section

Photograph Number: 7 of 9

APR 5 1976

4/30/76

Sussex County, Delaware



Property Name: Spring Banke  
Location: Clarksville, Delaware

Photographer: Brent Clark

Date: February 1976

Location of Negative: William Henry  
210 Pennsylvania Ave.  
Dover, Delaware

Description: Interior framing, rafter  
showing pitsaw marking, original  
section

Photograph Number: 8 *4/9*

APR 5 1976

*4/30/76*

*Sussex County, Delaware*





Property Name: Spring Banke  
Location: Clarksville, Delaware  
Photographer: Brent Clark  
Date: February 1976  
Location of Negative: William Henry  
210 Pennsylvania Ave.  
Dover, Delaware  
Description: Interior east wall of later  
section, stairwell  
Photograph Number: 9 <sup>1</sup>/<sub>9</sub>

APR 5 1976

4/30/76

Sussex County, Delaware