


# M. E. HELME HOUSE FURNISHING CO.



LA FIESTA  
DE LAS  
FAMILIAS  
MAY 1 TO 11 1907



HELME-WORTHY RESIDENCE AND STORE  
513-519 Walnut Street and 128 Sixth Street  
Huntington Beach, Ca 92648  
Orange County

Photographer: Unknown

Taken: 1907

Negative location: Susan Lucio  
same address

Front facade of store taken in 1907. The only changes from this photo are the sign across the top of the cornice and the plain doors in the center which replace the original.



HELME-WORTHY STORE AND RESIDENCE

513-519 Walnut Street and 128 Sixth Street

Huntington Beach, Ca 92648

Orange County

Photographer: Unknown

Taken: 1912

Negatives located: Susan Lucio

same address

1912 photograph of the Helme House Furnishing Company taken in 1912. Event and persons in picture unidentified. Note back of store with second floor porch. The sign "furnished rooms" refers to the second floor of the store building

RNITURE



HELME-WORTHY STORE AND RESIDENCE  
513-519 Walnut and 128 Sixth Street  
Huntington Beach, Ca 92648

Orange County

Photographer: Unknown

Taken: Ca. 1905

Negatives located: Susan Lucio  
same address

Front (Sixth St.) facade on right with Walnut facade on left. Store at rear faces Walnut. At this point, the front porch of the house had not been enclosed and the bay window built on the Walnut side. Porch at rear had not been enclosed yet and manufactured-stone-fronted addition to store had not been built yet.



HELME-WORTHY STORE AND RESIDENCE

513-518 Walnut Street and 128 Sixth Street

Huntington Beach, CA 92648

Orange County

Photographer: Unknown

Taken: Between 1909 and 1912

Negatives Stored: Susan Lucio

same address

View of front porch from northwest. Front facade with porch enclosed. Mollie Helme (seated). Side of porch nearest west side (right side) has been enclosed with louvers which will soon be removed. A fence has been added to the right (west) side yard.





HELME-WORTHY STORE AND RESIDENCE

513-519 Walnut Street amd 128 Sixth Street

Huntington Beach, Ca 92648

Orange County

Photographer: Unknown

Taken: Ca 1907

Negatives located: Susan Lucio  
same address

Walnut Street side of house approximately 1907. Bay window was a then-recent addition to existing house. Back porch had not been enclosed at this time. Yard and setting were about the same as they are at present.



My Mother  
He love

HELME-WORTHY STORE AND RESIDENCE  
513-519 Walnut and 128 Sixth Street  
Huntington Beach, CA 92648

Orange County

Photographer: Unknown

Taken: Ca. 1905

Negatives located: Susan Lucio  
same address

Interior of store ca. 1906-08. Mollie Helme  
on left and Matthew Helme on stairs in center.  
Walls have been built where the structural  
supports are visible on the right, and in  
front of the balcony.



HELME-WORTHY STORE AND RESIDENCE

513-519 Walnut Street and 128 Sixth Street  
Huntington Beach, CA 92648

Orange County

Photographer: Guy Guzzardo

Taken: May 1986

Location of negatives: Susan Lucio  
same address

Front facade of store building, from east.

All architectural elements are original except center front doors.



HELME-WORTHY STORE AND RESIDENCE

513-519 Walnut Street and 128 Sixth Street

Huntington Beach, CA 92648

Orange County

Photographer: Guy Guzzardo

Taken: May 1986

Negatives located: Susan Lucio

same address

Front facade of store (on right) faces east.

side facade (on left) faces south, on the  
alley





HELME-WORTHY STORE AND RESIDENCE

513-519 Walnut Street and 128 Sixth Street  
Huntington Beach, CA 92648

Orange County

Photographer: Guy Guzzardo

Taken: May 1986

Negatives located: Susan Lucio  
same address

Rear facade of store taken from northwest. Single-story shed-style addition on right is back end of manufactured-stone-fronted addition. Porch at top level is original with two additional enclosed porches on the first and second levels added at a later time. Edge of 1949 garage/apartment seen on right.



HELME-WORTHY STORE AND RESIDENCE

513-519 Walnut Street and 128 Sixth Street

Huntington Beach, CA 92648

Orange County

Photographer: Guy Guzzardo

Taken: May 1986

Negatives located: Susan Lucio

same address

View from corner of Walnut and sixth, looking southwest. Front and north side of store and front and east side of house, with the manufactured stone front between,



HELME-WORTHY STORE AND RESIDENCE

513-519 Walnut Street and 128 Sixth Street

Huntington Beach, CA 92648

Orange County

Photographer: Guy Guzzardo

Taken: May 1986

Negatives located: Susan Lucio

same address

Corner of Sixth and Walnut (along left side)

Porch glassed in before 1917. Shutters and  
louvers on side of porch will be removed soon



HELME-WORTHY STORE AND RESIDENCE

513-519 Walnut Street and 128 Sixth Street

Huntington Beach, CA 92648

Orange County

Photographer: Guy Guzzardo

Taken: May 1986

Negatives Located: Susan Lucio

same address

Front and west (right) side of house, looking southeast from Sixth Street. Side of store can be seen in background. Glassed in porch on house was done before 1917. Shutters and louvered wood on side of porch will be removed in the near future. "Back" yard is on west side of house.





HELME-WORTHY STORE AND RESIDENCE

513-519 Walnut Street and 128 Sixth Street

Huntington Beach, CA 92648

Orange County

Photographer: Guy Guzzardo

Taken: May 1986

Negatives Located: Susan Lucio  
same address

North side of store from Walnut Street, looking southwest. This is the east or Walnut side of the house. The manufactured stone addition in the center is attached to the north side of the store and has a shed-style roof.



HELME WORTHY STORE AND RESIDENCE

513-519 Walnut Street and 128 Sixth Street

Huntington Beach, CA 92648

Orange County

Photographer: Guy Guzzardo

Taken: May 1986

Negatives located: Susan Lucio

same address

Garage/Apartment at rear of property is not visible from front (Walnut Street) and mostly hidden by the wooden side-yard fence to the west of the house on the Sixth Street side.



HELME-WORTHY HOUSE

513-519 Walnut Street and 128 Sixth St.  
Huntington Beach, CA 92648

Orange County

Photographer: Guy Guzzardo

Taken: May 1986

Location of negatives: Susan Lucio, same  
address

Stairway in store building, looking west  
from bottom. Stair is in center of building  
and runs front to back



HELME-WORTHY STORE AND RESIDENCE

513-519 Walnut St. and 128 Sixth St.

Huntington Beach, CA 92648

Orange County

Photographer: Guy Guzzardo

Taken: May 1986

Second floor hallway, looking to the rear,  
with porch at rear and skylight above, center  
(Looking west)

Negatives stored: Susan Lucio, same address





HELME-WORTHY STORE AND RESIDENCE

513-519 Walnut street and 128 Sixth Street

Huntington Beach, CA 92648

Orange County

Photographer: Guy Guzzardo

Taken: May 1986

Location of negatives: Susan Lucio, same  
address

Skylight in center of second floor of store  
building is original, and made of wire glass  
in metal frames. Looking west



HELME-WORTH STORE AND RESIDENCE

513-519 Walnut Street and 128 Sixth Street  
Huntington Beach, Ca 92648

Orange County

Photographer: Guy Guzzardo

Taken: May 1986

Location of negatives: Susan Lucio, same  
address

In store building, original bathroom, looking northwest, in rear corner of building.