

HARDWARE

1903



1. Curtis Hardware Co
2. 2028 Grand Ave - PAONIA, CO. - DELTA CO
3. CINDY HARTLINE
4. 5-1-89
5. POSSESSION - HARTLINE
6. FRONT of Bldg - view W.

Photo #1

228

A black and white photograph of a building's entrance. The central feature is a pair of white double doors with glass inserts. Above the doors is a dark horizontal panel with the number '228' in white. The entrance is flanked by large, multi-paned windows with white frames. The windows reflect the surrounding environment, including a building and trees. The overall style is classic and somewhat formal.

1. CURD'S HARDWARE Co.
2. 228 GRAND AVE - PAONIA, Co - DELTA
3. C. HARTLINE
4. - 6 - 1 - 89
5. HARTLINE
6. CLOSE-up FRONT Bldg.
PHOTO # 2



1903

MWA

V
Ho

1. CURTIS HARDWARE CO.
2. 207 GRAND AVE. PAONITA, Co. - DISTRICT
2. ~~CHARTER LINE~~
4. 6-1-89
5. HARTLINE
6. WIDE-ANGLE, FRONT OF Bldg.
View W
(NOTE: Bldg NEXT door DATE 1903
1st Bank.)

Photo #3



1. CURTISS HARDWARE CO.
2. 228 GRAND AVE. FRONT CO - DELTA CO
3. C. LARSEN
4. 6-1-89
5. POSSESSION - HARTLINE
6. CLOSE-UP - FRONT OF BLDG. - DETAIL

PHOTO #4



1. CURTIS HARDWARE Co.
2. AIR CONDITIONING - PHONIX, Co - DELTA, Co
3. ~~PHONIX, Co~~
- 4 6-1-89
- 5 PHONIX, Co
6. NEAR (NEW) Bldg. view E.

Photo #5



1. Cushing Construction Co
2. 228 GRAND AVE - FRONT, S - 12/1/89
3. C. HARTLINE
4. 6-1-89
5. C. HARTLINE
4. In Front of Bldg. Pointing down
GRAND AVE. South.

Photo #6



1. CURTIS HARDWARE Co
2. 228. GRAND AVE. BOSTON, Co. DECHA Co
3. C. HARTLINE
4. 6-1-89
5. C. HARTLINE
6. STAIRCASE to UPSTAIRS

Photo # 7



1. CURTIS HARDWARE Co
2. 228 GRAND AVE - PRONIA, Co - DELTA Co
3. C HARTLINE
- 4 6-1-89
- 5 C. HARTLINE,
6. BRASS DUST COLLECTORS ON STAIRS
Photo #8



1. CURTIS HARDWARE Co.
2. 228 GRAND AVE - HONOLULU, Co - DELTA Co.
3. HARTLING
4. 6-1-89
5. HARTLING
6. UPSTAIRS APT - FRONT DOOR.

Photo H9



1. CURTIS HUNTER & Co

2. 228. C. H. AND A. H. - HOMER, Co-DELTA

3. C. HARTLINE

4. 6-1-89

5. HARTLINE

6. 1 of 3 SETS LOCKET DOORS in
APT.

Photo # 10



1. CURTIS HARDWARE Co.
 2. 228 GRAND AVE. PAONIA, CO - DELTA
 3. C. HARTLINE
 4. 6-1-89
 5. HARTLINE
 6. ORIGINAL FIREPLACE IN RECEPTION
Room - MISSING PIECES ARE
accounted FOR.
- Photo # 11



1. CURTIS HARDWARE Co
2. 228 GRAND AVE - PAONIA, CO - DELTA
3. C. HARTLINE
4. 6-1-89
5. HARTLINE
6. Standing in dining Room - Looking thru 3 sets of pocket doors to bay window in front of Bldg.
photo #12



1. CURTIS HARDWARE Co.
2. 228 GRAND AVE - PAONIA, CO - DELTA
3. C. HARTLINE
4. 6-1-89
5. HARTLINE
6. BAY WINDOW in Living Room
FACING FRONT OF Bldg.
Photo # 13



1. CURTIS. HARDWARE
2. 228 GRAND AVE - PAONIA, CO - DELTA
- 3 C HARTLINE
- 4 6-1-89
- 5 HARTLINE
6. 1 OF 3 SIMILAR LIGHT FIXTURES

Photo #14



1. CURTIS HARDWARE Co.
2. 228 GRAND AVE. PAONIA, Co DELTA
3. C. HARTLINE
4. 6-1-89
5. HARTLINE
6. BLT-IN IN CLOSET OF A
BEDROOM

PHOTO #15



1. CURTIS HARDWARE Co
2. 228 GRAND AVE - PAONIA, Co. DELTA Co
3. C. HARTLINE
4. 6-1-89
5. HARTLINE
6. SKYLIGHT IN UPSIDE APT

Photo #16



1. CURTIS HARDWARE Co
2. 228 GRAND AVE - PAONIA, Co - Delta
3. C. HARTLINE
4. 6-1-89
5. HARTLINE
6. 1 of many dormer windows
& molding with ROSETTES
Thru-out apt.
Photo # 111




1. CURT'S HARDWARE CO.
2. 228 GRAND AVE PADONIA, CO - DELTA
3. C. HARTLINE
4. 6-1-89 photo # 18
5. HARTLINE
6. Door in dining room LEADS to BACK STAIRWELL. GLASS PANEL IN DOOR HAS ORNATE ETCHED GLASS DESIGN. THE BELL RINGS WHEN ELEVATOR RISES IN FRONT OF DOOR.



1. CURT'S HARDWARE Co.
2. 228 GRAND AVE. PAONIA, Co. DELTA
3. C. WARTLINE
4. 6-1-89
5. WARTLINE
6. BLT - IN CHINA CABINET IN
DINING ROOM PASSES THRU
to KITCHEN. ALSO, SWINGING
door to KITCHEN
Photo # 19



1. CURTIS HARDWARE Co.
 2. 228 GRAND AVE. - PRONIA, CO - DELTA 
 3. C. HARTLINE
 4. 6-1-89
 5. HARTLINE
 6. SKY LIGHTS in dining room.
(ROOF in NEED OF REPAIR)
- Photo #20



1. CURTIS HARDWARE Co
2. 228 GRAND AVE - PAONIA, CO - DELTA
3. C. HARTLINE
- 4 6-1-89
5. HARTLINE
6. TIN GEILING IN KITCHEN
imported FROM CHINA

Photo # 21



1. CURTIS HARDWARE CO
2. 228 GRAND AVE - PAONIA, CO - DELTA
3. C. HARTLINE
4. 6-1-89
5. HARTLINE
6. BLT IN BAKING CENTER IN
KITCHEN

PHOTO # 22



1. CURTIS HARDWARE Co.
2. 228 GRAND AVE - PAONIA, Co. - DELTA
3. C. HARTLINE
4. 6-1-89
5. HARTLINE
6. BATH-TUB IN BATHROOM
LOCATED IN REAR OF Bldg
OFF KITCHEN.

1 photo # 23



1. CURTIS HARDWARE Co.

2. 228 GRAND AVE. HOVIA, Co - Delta Co

3. Cindy HARTLINE

4. 6-1-89

5. POSSESSION - HARTLINE

6. MAIN FLOOR - OUTLINE TRIM OF TIN
CEILING

Photo # 24



1. CURTIS HARDWARE CO. -

2. 228 GRAND AVE - PAONIA, CO - DELTA CO.

3. CINDY HARTLINE

4. 6-1-89

5. POSSESSION - HARTLINE

6. INSIDE BLDG - MAIN FLOOR, POINTING TO
FRONT DOOR ENTRANCE

PHOTO # 25



1. Curtis HARDWARE Co.
2. 228 G. RAND AVE + RAINIA, Co - DELTA, Co
3. Cindy HARTLINE
4. 6-1-89
5. Possession - HARTLINE
6. Main Floor - Tin Ceiling

Photo # 26



1. CURT'S HARDWARE Co.
2. 228 Grand Ave. - Detroit, Co. - Detroit Co.
3. CINOX Hardware Co.
4. 6-1-80
5. POSSESSION - HARFLINE
6. MAIN FLOOR - Grade for VENTILATION

Photo # 27




1. CURTISS HARDWARE CO
2. 228 GRAND AVE. - PAONIA, CO - DELTA CO
3. CINDY HARTLINE
4. 6-1-89
5. POSSESSION - HARTLINE
6. MAIN FLOOR - FACING REAR DOORS

Photo # 28



1. CURTISS HARDWARE CO
2. 228 GRAND AVE - PAONIA, Ia - DELTA Co
3. CINDY HARTLINE
4. 6-1-89
5. POSSESSION - HARTLINE
6. MAIN FLOOR - AIMED AT SUSPENDED ELEVATOR.

Photo # 29



- 1 CURTIS HARDWARE
2. 228 GRAND AVE
3. CINDY HARTLINE
4. 6-1-89
5. POSSESSION - HARTLINE
6. MAIN FLOOR - COAL FURNACE GRADE

Photo #30



1. CURTIS HARDWARE CO
2. 228 GRAND AVE. MONROE, Co - DELTA Co.
3. CINDY HARTLINE
4. 6-1-89
5. POSSESSION - HARTLINE
6. Main Floor - REAR - FREIGHT ELEVATOR

Photo # 34