

1) Name of Property: Grants Pass Supervisor's Warehouse, Office #2207 2) City and State: Grants Pass, OR 3) Photographer: Janet Joyer 4) Date: 6/27/85 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files. 6) Description: Looking northwest, view of east-facing main facade and left elevation 7) Photograph Number: 11-S0-2207-1



1) Name of Property: Grants Pass Supervisor's Warehouse, Galice Warehouse #2205 2) City and State: Grants Pass, OR 3) Photographer: Janet Joyer 4) Date: 6/27/85 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files. 6) Description: Looking west, view of main east-facing facade 7) Photograph Number: 11-S0-2205-1



1) Name of Property: Grants Pass Supervisor's Warehouse, Vehicle Storage #2309 2) City and State: Grants Pass, OR 3) Photographer: Janet Joyer 4) Date: 6/27/85 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files. 6) Description: Looking southwesterly, view of main east-facing facade 7) Photograph Number: 11-S0-2309-1



1) Name of Property: Grants Pass Supervisor's Warehouse, Equipment Storage #2310 2) City and State: Grants Pass, OR 3) Photographer: Janet Jover 4) Date: 6/27/85 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files. 6) Description: Looking northeast, view of main west-facing facade 7) Photograph Number: 11-S0-2310-1



1) Name of Property: Grants Pass Supervisor's Warehouse, Machine Shop #2101 2) City and State: Grants Pass, OR 3) Photographer: Janet Joyer 4) Date: 6/27/85 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files. 6) Description: Looking west, view of east gable end 7) Photograph Number: 11-S0-2101-3



1) Name of Property: Grants Pass Supervisor's Warehouse, Machine Shop #2101 2) City and State: Grants Pass, OR 3) Photographer: Janet Joyer 4) Date: 6/27/85 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files. 6) Description: Looking south, view of north-facing rear elevation 7) Photograph Number: 11-S0-2101-1



1) Name of Property: Grants Pass Supervisor's Warehouse, Machine Shop #2101 2) City and State: Grants Pass, OR 3) Photographer: Janet Joyer 4) Date: 6/27/85 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files. 6) Description: Looking east, view of west gable end 7) Photograph Number: 11-S0-2101-2



1) Name of Property: Grants Pass Supervisor's Warehouse, Gas House #2501 2) City and State: Grants Pass, OR 3) Photographer: Janet Joyer 4) Date: 6/27/85 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files. 6) Description: Looking southwest, view of main facade and left elevation 7) Photograph Number: 11-S0-2501-1



1) Name of Property: Grants Pass Supervisor's Warehouse, Engineering Warehouse #2206 2) City and State: Grants Pass, OR 3) Photographer: Janet Joyer
4) Date: 6/27/85 5) Negative Location: USDA Forest Service, Regional Office, Recreation Unit, CRM files. 6) Description: Looking east, view of main west-facing facade 7) Photograph Number: 11-S0-2206-1