



Borden Mines Superintendent's House (AL-V-A-011)

Frostburg vicinity, Allegany County

Photo: Peter Kurtze, January 1984

Negatives at Maryland Historical Trust

21 State Circle, Annapolis MD

21401

view from east

1/8



Borden Mines Superintendent's House (AL-V-A-011)

Frostburg vicinity, Allegany County

Photo: Peter Kurtze, January 1984

Negatives at Maryland Historical Trust

21 State Circle, Annapolis, MD

21401

view from north ~~west~~ east

2/8



Borden Mines Superintendent's House (AL-V-A-011)

Frostburg vicinity, Allegany County

Photo: Peter Kurtze, January 1984

Negatives at Maryland Historical Trust

21 State Circle, Annapolis, MD

21401

parlor fireplace

3/8



Borden Mines Superintendent's House (AL-V-A-011)

Frostburg vicinity, Allegany County

Photo: Peter Kurtze, January 1984

Negatives at Maryland Historical Trust

21 State Circle, Annapolis, MD

21401

master bedroom fireplace

4/8



Borden Mines Superintendent's House (AL-V-A-011)
Frostburg vicinity, Allegany County

Photo: Peter Kurtze, January 1984

Negatives at Maryland Historical Trust
21 State Circle, Annapolis, MD

fireplace in southeast room

21401



Borden Mines Superintendent's House (AL-V-A-011)

Frostburg vicinity, Allegany County

Photo: Peter Kurtze, January 1984

Negatives at Maryland Historical Trust

21 State Circle, Annapolis, MD

stair hall, view from south

21401

6/8



Borden Mines Superintendent's House (AL-V-A-011)

Frostburg vicinity, Allegany County

Photo: Peter Kurtze, January 1984

Negatives at Maryland Historical Trust

21 State Circle, Annapolis, MD

21401

second-story landing, view from NW

7/8



Borden Mines Superintendent's House (AL-V-A-011
Frostburg vicinity, Allegany County

Photo: Ronald L. Andrews, September 1974

Negative at Maryland Historical Trust

21 State Circle, Annapolis, MD

southeast facade before rehabilitation 21301

8/8