

Daniels Farm House

Big Bend National Park, Texas

Tom Vitanza November 1984

NPS/ Southwest Region Office

Santa Fe, New Mexico

East elevation view of doorway (facing west)

Photo Number 1



Daniels Farm House

Big Bend National Park, Texas

Tom Vitanza November 1984

NPS/ Southwest Region Office

Santa Fe, New Mexico

View of southern elevation exposed vigas &
caneles. (camera facing north)

Photo Number 2



Daniels Farm House

Big Bend National Park, Texas

Tom Vitanza November 1984

NPS/ Southwest Region Office

Santa Fe, New Mexico

View of NW corner showing both north elevation and west elevation. (facing southeast)

Photo Number 3



Daniels Farm House

Big Bend National Park, Texas

Tom Vitanza November 1984

NPS/ Southwest Region Office

Santa Fe, New Mexico

View of west elevation showing doorway.

(camera facing east)

Photo Number 4



Daniels Farm House

Big Bend National Park, Texas


Tom Vitanza November 1984

NPS/ Southwest Region Office

Santa Fe, New Mexico

View of SE elevation (camera facing NW)

Photo Number 5



Daniels Farm House


Big Bend National Park, Texas

Tom Vitanza November 1984

NPS/ Southwest Region Office

Santa Fe, New Mexico

Interior view of cane and viga roof construction. Note deterioration & graffiti (facing east). Photo Number 6



Daniels Farm House

Big Bend National Park, Texas

Tom Vitanza November 1984

NPS/ Southwest Region Office

Santa Fe, New Mexico

View of roof construction (restabilized in
1972).

Photo Number 7