



Photo #1

Hurricane / LaVerkin Bridge

Hurricane, Washington County, Utah

November 1994

A black and white photograph of a steel truss bridge. The bridge is supported by a large, dark, diagonal steel beam. A sign with the text "BRIDGE CLOSED" is attached to the bridge structure. The bridge spans a deep, rocky gorge. The background shows a steep, rocky hillside. The overall scene is dark and somewhat desolate.

**BRIDGE CLOSED**

Photo #2

Hurricane/Lakeview Bridge

Hurricane, Washington County, Utah

November 1994