


Photographer: James R. Lockhart Negatives Filed: Georgia Department of Natural Resources Date: February, 1981 Description (1 of 8): Front facade; photographer facing southwest.



Photographer: James R. Lockhart Negatives Filed: Georgia Department of Natural Resources Date: February, 1981 Description (2 of 8): Rear of fail: photographer facing north.



Photographer: James R. Lockhart Negatives Filed: Georgia Department of Natural Resources Date: February, 1981 Description (3 of 8): Detail of southeast wall, photographer facing northwest.




Photographer: James R. Lockhart Negatives Filed: Georgia Department of Natural Resources Date: February, 1981 Description (4 of 8): First floor, jailer's quarters; photographer facing north




Photographer: James R. Lockhart Negatives Filed: Georgia Department of Natural Resources Date: February, 1981 Description (5 of 8): First floor, jail entrance; photographer facing west.



Photographer: James R. Lockhart Negatives Filed: Georgia Department of Natural Resources Date: February, 1981 Description (6 of 8): Second floor, room; photographer facing north.



Photographer: James R. Lockhart Negatives Filed: Georgia Department of Natural Resources Date: February, 1981 Description (7 of 8): Second Floor.ccellblock; photographer facing southwest.



Photographer: James R. Lockhart Negatives Filed: Georgia Department of Natural Resources Date: February, 1981 Description (8 of 8): Second Floor, cellblock; photographer facing southwest.