

Lava Rock Structures in South Central Idaho Graves, Lulu, Farm, site 94 (house)

Two miles north, one mile west, and one-half mile north of Jerome Jerome vicinity, Jerome County, Idaho

Photograph by Jennifer Eastman Attebery June 1983

Negative on file at the Idaho State Historical Society, Boise, Idaho

View from east

Photograph one of three



Lava Rock Structures in South Central Idaho Graves, Lulu, Farm, site 94 (cattle shed)

Two miles north, one mile west, and one-half mile north of Jerome Jerome vicinity, Jerome County, Idaho

Photograph by Jennifer Eastman Attebery June 1983

Negative on file at the Idaho State Historical Society, Boise, Idaho

View from south

Photograph two of three



Lava Rock Structures in South Central Idaho Graves, Lulu, Farm, site 94 (poultry house)

Two miles north, one mile west, and one-half mile north of Jerome Jerome vicinity. Jerome County. Idaho

Photograph by Jennifer Eastman Attebery June 1983

Negative on file at the Idaho State Historical Society, Boise, Idaho

View from east

Photograph three of three