



Number:

19 22

Photographer:

Terry Barnhart

Date of Photo:

3-1-77

Negatives

Gage Davis and Associates,

Filed:

1215 Spruce, Boulder, CO.

Description:

Cottages #413, 411, 409,
looking East.

MAR 21 1978

AUG 24 1977



Number:

2022

Photographer: Terry Barnhart

Date of Photo: 3-1-77

Negatives Gage Davis & Associates

Filed:

1215 Spruce

Boulder, CO 80302

Description: Wild Rose Cottage, looking
southeast

MAR 21 1978

AUG 24 1977



MAR 21 1978

AUG 24 1977

Number: 3 8 22
Photographer: Terry Barnhart
Date of Photo: 12-13-76
Negatives: Gage Davis and Associates,
Filed: 1215 Spruce, Boulder, CO.

Description: Looking Northeast,
general overview of Chautauqua
from mesa West of grounds; Auditorium
in center of picture.



Number: 4 8 22
Photographer: Terry Barnhart
Date of Photo: 12-13-76
Negatives: Gage Davis and Associates,
Filed: 1215 Spruce, Boulder, CO.

Description: Looking South through
walk-entrance of park toward the
Dining Hall.

MAR 21 1978

AUG 24 1977



Number: 5 2 22
Photographer: Terry Barnhart
Date of Photo: 12-13-76
Negatives Gage Davis and Associates,
Filed: 1215 Spruce, Boulder, CO.

Description: View of the Auditorium
looking Southwest.

MAR 21 1978

AUG 24 1977



Number: 6 2 22
Photographer: Terry Barnhart
Date of Photo: 12-13-76
Negatives Gage Davis and Associates,
Filed: 1215 Spruce, Boulder, CO.

Description: Looking West by
Northwest toward the
Dining Hall.

MAR 21 1978

AUG 24 1977



Number: 7 8 22
Photographer: Terry Barnhart
Date of Photo: 12-13-76
Negatives Gage Davis and Associates,
Filed: 1215 Spruce, Boulder, CO.

Description: The Administration
Building looking

MAR 21 1978

Northeast. AUG 24 1977



Number: 8222
Photographer: Terry Barnhart
Date of Photo: 12-13-76
Negatives Gage Davis and Associates,
Filed: 1215 Spruce, Boulder, CO.

Description: The Community House
looking West.

MAR 21 1978

AUG 24 1977



ONE WAY
DO NOT
ENTER

Number: 9 8 22
Photographer: Terry Barnhart
Date of Photo: 12-13-76
Negatives Gage Davis and Associates,
Filed: 1215 Spruce, Boulder, CO.

Description: The Wild Rose Lodge
looking West.

MAR 21 1978

AUG 24 1977



MAR 21 1978

Number: 10 of 22
Photographer: Terry Barnhart
Date of Photo: 12-13-76

Negatives Gage Davis and Associates,
Filed: 1215 Spruce, Boulder, CO.

AUG 24 1977

Description: Looking Northeast
at the Columbine Lodge.



Number: 11 8 22
Photographer: Terry Barnhart
Date of Photo: 12-13-76
Negatives Gage Davis & Associates
Filed: 1215 Spruce
Boulder, CO 80302
Description: Cottage #304, looking
east

MAR 21 1978

AUG 24 1977



MAR 21 1978

AUG 24 1977

Number: 12 ~~18~~ 22
Photographer: Terry Barnhart
Date of Photo: 12-13-76
Negatives Gage Davis and Associates,
Filed: 1215 Spruce, Boulder, CO.

Description: Looking West on
Clematis Drive, cottage numbers
beginning in foreground are 102,
106, 108, 110, 114 and 35.



Number: 13 ²²
Photographer: Terry Barnhart
Date of Photo: 12-13-76
Negatives Gage Davis and Associates,
Filed: 1215 Spruce, Boulder, CO.

Description: Looking Southwest toward
the 100 row and the Flatirons on
Green Mountain.

MAR 21 1978

AUG 24 1977



MAR 21 1978

AUG 24 1977

Number: 14 ~~0~~ 22
Photographer: Terry Barnhart
Date of Photo: 12-13-76
Negatives: Gage Davis and Associates,
Filed: 1215 Spruce, Boulder, CO.

Description: Looking Southwest at
cottage #302 in foreground and
cottage #300 in left-background.



AUG 24 1977

Number: 15 ~~9~~ 22
Photographer: Terry Barnhart
Date of Photo: 12-13-76
Negatives Gage Davis and Associates,
Filed: 1215 Spruce, Boulder, CO.

Description: Looking South on
Goldenrod Drive.

MAR 21 1978



Number:

16 ~~8~~ 22

Photographer:

Terry Barnhart

Date of Photo:

12-13-76

Negatives

Gage Davis and Associates,

Filed:

1215 Spruce, Boulder, CO.

Description:

Looking South on
Kinickinick Drive.

MAR 21 1978

AUG 24 1977



Number: 17 ~~0~~ 22
Photographer: Terry Barnhart
Date of Photo: 3-1-77
Negatives Gage Davis and Associates,
Filed: 1215 Spruce, Boulder, CO.

Description: Chautauqua Park Looking
Northeast.

MAR 21 1978

AUG 24 1977




Number: 18 ~~8~~ 22
Photographer: Terry Barnhart
Date of Photo: 3-1-77
Negatives Gage Davis and Associates,
Filed: 1215 Spruce, Boulder, CO.

Description: Chautauqua Park looking
East.

MAR 21 1978

AUG 24 1977



Number: 19 ⁸ 22
Photographer: Terry Barnhart
Date of Photo: 3-1-77
Negatives: Gage Davis and Associates,
Filed: 1215 Spruce, Boulder, CO.

Description: Chautauqua Park looking
Northeast.

MAR 21 1978

AUG 24 1977



Number: 20 ~~5~~ 22
Photographer: Terry Barnhart
Date of Photo: 3-1-77
Negatives Gage Davis and Associates,
Filed: 1215 Spruce, Boulder, CO.

Description: Chautauqua Park entrance
and Shelter House.

AUG 24 1977

MAR 21 1978



Number: 21 8 22
Photographer: Terry Barnhart
Date of Photo: 3-1-77
Negatives: Gage Davis and Associates,
Filed: 1215 Spruce, Boulder, CO.
Description: Cottage #29 looking West.

MAR 21 1978

AUG 24 1977



Number: 22 ~~9~~ 22
Photographer: Terry Barnhart
Date of Photo: 3-1-77
Negatives Gage Davis and Associates,
Filed: 1215 Spruce, Boulder, CO.
Description: Cottage #23 looking West.

AUG 24 1977

MAR 21 1978