



Mills, Lewis H., House (1916)
2039 NW Irving Street
Portland, Multnomah County, Oregon

1 of 6

South (front) elevation

Alfred M. Staehli photograph, 1981

317 SE 62nd Avenue
Portland, OR 97215



Mills, Lewis H., House (1916)
2039 NW Irving Street
Portland, Multnomah County, Oregon

2 of 6 later
Original Doric portico/installed in
Lewis Mills House in Dunthorpe,
Portland, 1938.
Walter Boychuk photograph, undated.

Oregon Historical Society negative
#42239
1230 SW Park Avenue
Portland, OR 97205



Mills, Lewis H., House (1916)
2039 NW Irving Street
Portland, Multnomah County, Oregon

3 of 6

North (rear) elevation, showing recent
solarium addition consistent with
Secretary's Standards.

Alfred M. Staehli photograph, 1981
317 SE 62nd Avenue
Portland, OR 97215



Mills, Lewis H., House (1916)
2039 NW Irving Street
Portland, Multnomah County, Oregon

4 of 6

Entry stair hall. Stair handrail is original. Balusters are replacements for those removed to Dunthorpe in 1938.

Alfred M. Staehli photograph, 1981
317 SE 62nd Avenue
Portland, OR 97215



Mills, Lewis H., House (1916)
2039 NW Irving Street
Portland, Multnomah County, Oregon

5 of 6

Interior of original dining room in
SW corner of ground story. Classical
cornice molding and dado are recon-
structed. Mantelpiece is original.

Alfred M. Staehli photograph, 1981
317 SE 62nd Avenue
Portland, OR 97215



Mills, Lewis H., House (1916)
2039 NW Irving Street
Portland, Multnomah County, Oregon

6 of 6

Upstairs bedrooms remodeled as living
area c. 1955.

Alfred M. Staehli photograph, 1981
317 SE 62nd Avenue
Portland, OR 97215