



Trinity Presbyterian Church
(Mission United Pres. Church)
3261 - 23rd St., San Francisco, Calif.

Photo taken 4/27/80 by
Winchell T. Hayward

Negative located at 208 Willard North,
San Francisco

Outside view of church showing main
entrance (facing southwest from east
side of Capp St.)

Photograph #1 of 10

JAN 20 1982



Trinity Presbyterian Church
(Mission United Pres. Church)
3261 - 23rd St., San Francisco, Calif.

Photo taken 4/27/80 by
Winchell T. Hayward

Negative located at 208 Willard North
San Francisco

View of rear and east side of church,
facing northwest from east side of
Capp St.

Photograph #2 of 10

JAN 20 1982

ED
CHURCH
PRESBYTERIAN

WESLEYAN
METHODIST
PRESBYTERIAN
CHURCH
WASHTON
ST. PAUL'S CHURCH
WASHTON
ST. JOHN'S CHURCH
WASHTON
ST. ANDREW'S CHURCH
WASHTON
ST. GEORGE'S CHURCH
WASHTON

Trinity Presbyterian Church
(Mission United Pres. Church)
3261 - 23rd St., San Francisco, Calif.

Photo taken 4/27/80 by
Winchell T. Hayward

Negative located at 208 Willard North
San Francisco

Photograph of main entrance showing
central column and florid capital

Photograph #3 of 10

JAN 20 1982



Trinity Presbyterian Church
(Mission United Pres. Church)
3261 - 23rd St., San Francisco, Calif.
Phototaken 4/27/80 by
Wicnehl T. Hayward

Negative located at 208 Willard North,
San Francisco

View of hammer-beam ceiling and trusses,
main sanctuary, facing toward altar

Photograph #4 of 10

JAN 20 1982



Trinity Presbyterian Church
(Mission United Pres. Church)
3261 - 23rd St., San Francisco, Calif.

Photo taken 4/27/80 by
Winchell T. Hayward

Negative located at 208 Willard North
San Francisco

View of west side of balcony in sanctu-
ary, showing curvature and decorative
detail

Photograph #5 of 10

JAN 20 1982



Trinity Presbyterian Church
(Mission United Pres. Church)
3261 - 23rd St., San Francisco, Calif.

Photo taken 4/27/80 by
Winchell T. Hayward

Negative located at 208 Willard North
San Francisco

View of organ - taken from west front
part of balcony, facing south

Photograph #6 of 10

JAN 20 1982



Trinity Presbyterian Church
(Mission United Pres. Church)
3261 - 23rd St., San Francisco, Calif.

Photo taken 4/27/80 by
Winchell T. Hayward

Negative located at 208 Willard North
San Francisco

View of front rose window - facing NW -
from walled-off portion of balcony

Photograph #7 of 10

JAN 20 1982



Trinity Presbyterian Church
(Mission United Pres. Church)
3261 - 23rd St., San Francisco, Calif.

Photo taken 4/27/80 by
Winchell T. Hayward

Negative located at 208 Willard North
San Francisco

View of organ and west rose window,
facing northeast from balcony

Photograph #8 of 10

JAN 20 1982



Trinity Presbyterian Church
(Mission United Pres. Church)
3261 - 23rd St., San Francisco, Calif.


Photo taken 4/27/80 by
Winchell T. Hayward

Negative located at 208 Willard North
San Francisco

Stair railing detail - east stairway
up to balcony

Photograph #9 of 10

JAN 20 1982



Trinity Presbyterian Church
(Mission United Pres. Church)
3261 - 23rd St., San Francisco, Calif.

Photo taken 4/27/80 by
Winchell T. Hayward

Negative located at 208 Willard North,
San Francisco

Truss detail at ceiling of ground-floor
auditorium showing rod, saddles
and turnbuckle

Photograph #10 of 10

JAN 20 1982