



Lava Rock Structures in South Central Idaho  
Van Wagener, Jacob B., Barn, site 28

Four miles east and three miles south of Jerome  
Jerome vicinity, Jerome County, Idaho

Photograph by Marian Posey-Ploss  
Summer 1981

Negative on file at the Idaho State Historical Society,  
Boise, Idaho

View from northeast

Photograph one of four



J. B. VAN WAGENER, JEROME, IDAHO.  
-1887-8-20

Lava Rock Structures in South Central Idaho  
Van Wagener, Jacob B, Barn, site 28

Four miles east and three miles south of Jerome  
Jerome vicinity, Jerome County, Idaho

Photograph by Clarence Bisbee  
date unknown

Negative on file at the Idaho State Historical Society,  
Boise, Idaho

View from northeast

Photograph two of four



Lava Rock Structures in South Central Idaho  
Van Wagener, Jacob B., Barn, site 28

Four miles east and three miles south of Jerome  
Jerome vicinity, Jerome County, Idaho

Photograph by Marian Posey-Ploss  
Summer 1981

Negative on file at the Idaho State Historical Society,  
Boise, Idaho

View from southwest

Photograph three of four



Lava Rock Structures in South Central Idaho  
Van Wagener, Jacob B., Barn, site 28

Four miles east and three miles south of Jerome  
Jerome vicinity, Jerome County, Idaho

Photograph by Marian Posey-Ploss  
Summer 1981

Negative on file at the Idaho State Historical Society,  
Boise, Idaho

View from south

Photograph four of four