



GLOVER HOUSE
(Budd House)
Newtown, CT

H. Keiner Photo, 3/79
Negative with Connecticut Historical Commission
Hartford, CT

Main (west) facade, view northeast 1

FEB 11 1982

JAN 13 1982



GLOVER HOUSE
(Budd House)
Newtown, CT

H. Keiner Photo, 3/79
Negative with Connecticut Historical Commission
Hartford, CT

Main Street, looking north, Glover House in
foreground, view northeast 2

FEB 11 1982

JAN 12 1982



GLOVER HOUSE
(Budd House)
Newtown, CT

H. Keiner Photo, 3/79
Negative with Connecticut Historical Com-
mission, Hartford, CT

Carriage house, main facade, view north-
east

3

FEB 11 1982 JAN 12 1982



GLOVER HOUSE
(Budd House)
Newtown, CT

H. Keiner Photo, 3/79
Negative with Connecticut Historical Com-
mission, Hartford, CT

Interior, hallway, showing main and servants
stairways, view east 4

FEB 11 1982

JAN 12 1982



GLOVER HOUSE
(Budd House)
Newtown, CT

H. Keiner Photo, 3/79
Negative with Connecticut Historical Com-
mission, Hartford, CT

Interior, Hallway, showing doorway to north
parlor, view northeast 5

FEB 11 1982

JAN 12 1982



GLOVER HOUSE
(Budd House)
Newtown, CT

H. Keiner Photo, 3/79

Negative with Connecticut Historical Commission,
Hartford, CT

Interior, morning room, showing built-in
china closet and fireplace, view
southwest

6

FEB 11 1982

JAN 12 1982



GLOVER HOUSE
(Budd House)
Newtown, CT

H. Keiner Photo, 3/79
Negative with Connecticut Historical Com-
mission, Hartford, CT

Interior, third floor, showing water cis-
tern and king-post truss, view south-
east

7

FEB 11 1982

JAN 12 1982