



1 of 10

Hawthorn House

Mobile, Alabama

Robin A. Lang, Photographer

September, 1982

MHDC negative files

facade, camera facing north



2 of 10

Hawthorn House

Mobile, Alabama

Robin A. Lang, Photographer

September, 1982

MHDC negative files

east wing & east side of main house

camera facing northwest



3 of 10

Hawthorn House


Mobile, Alabama

Robin A. Lang, Photographer

September, 1982

MHDC negative files

rear of east wing & east side of
main house, camera facing west



4 of 10

Hawthorn House

Mobile, Alabama

Robin A. Lang, Photographer

September, 1982

MHDC negative files

west side of main house, camera
facing northeast



5 of 10

Hawthorn House

Mobile, Alabama

Robin A. Lang, Photographer

September, 1982

MHDC negative files

front entrance, camera facing
northwest



6 of 10

Hawthorn House

Mobile, Alabama

Robin A. Lang, Photographer

September, 1982

MHDC negative files

columns & balustrade of front
porch, camera facing southeast



7 of 10

Hawthorn House


Mobile, Alabama

Robin A. Lang, Photographer

September, 1982

MHDC negative files

detail of balustrade, camera
facing southeast



8 of 10

Hawthorn House

Mobile, Alabama

Robin A. Lang, Photographer

September, 1982

MHDC negative files

rear entrance, camera facing
southeast



9 of 10

Hawthorn House

Mobile, Alabama

Robin A. Lang, Photographer

September, 1982

MHDC negative files

parlor doors between west rooms,
camera facing northwest



10 of 10

Hawthorn House

Mobile, Alabama

Robin A. Lang, Photographer

September, 1982

MHDC negative files

typical fireplace, camera facing
west