

Photographer: Warren Jagger Date: June 1980 Negative filed at: Rhode Island Historical

Preservation Commission

150 Benefit Street Providence, R.I.

Exterior view facing southeasterly.

Photo #22



Photographer: Warren Jagger

Date: May 1983 Negative filed at: Rhode Island Historical

Preservation Commission

150 Benefit Street Providence, RI

View of the central hall facing southerly, showing the staircase.

Photo #22A



Photographer: Warren Jagger

Date: May 1983

Negative filed at: Rhode Island Historical

Preservation Commission

150 Benefit Street Providence, RI

View of the parlor facing southeasterly, with the dining room in the background at the right.

Photo #22B



Photographer: Warren Jagger Date: May 1983 Negative filed at: Rhode Isl Rhode Island Historical

Preservation Commission

150 Benefit Street Providence, RI

View of the library facing southwesterly.

Photo #22C



Photographer: Warren Jagger

Date: May 1983

Negative filed at: Rhode Island Historical

Preservation Commission

150 Benefit Street Providence, RI

General view of outbuildings facing southerly along the driveway, showing (from right-foreground to background) the corn crib, the hen house, the wash room and attached box stalls, and the barn-like "cider mill".

Photo #22D



Photographer: Warren Jagger Date: May 1983 Negative filed at: Rhode Is:

Rhode Island Historical

Preservation Commission

150 Benefit Street Providence, RI

Exterior view of the water tower, facing northerly.

Photo #22E