



NOV 28 1978

Portsmouth Friends Meeting House
Portsmouth, Rhode Island

Warren Jagger, Photographer October, 1977
Negative: Rhode Island Historical Preservation
Commission

View of the meeting house from the east
northeast, showing vestibule and office
additions.

OCT 10 1978

Photo #1



NOV 28 1978

Portsmouth Friends Meeting House:
Parsonage
Portsmouth, Rhode Island

Ancelin Lynch, Photographer August, 1978
Negative: Rhode Island Historical Preservation Commission

View of the parsonage from the east.

Photo #2

OCT 10 1978



NOV 28 1978

Portsmouth Friends Meeting House
Portsmouth, Rhode Island

Warren Jagger, Photographer October, 1977
Negative: Rhode Island Historical Preservation
Commission

Interior view looking northeast inside men's
meeting room.

OCT 10 1978

Photo #3



NOV 28 1978

Portsmouth Friends Meeting House
Portsmouth, Rhode Island

Warren Jagger, Photographer October, 1977
Negative: Rhode Island Historical Preservation
Commission

Interior view looking northwest from the
gallery in the main meeting room toward the
women's meeting.

OCT 10 1978

Photo #4



NOV 28 1978

Portsmouth Friends Meeting House
Portsmouth, Rhode Island

Warren Jagger, Photographer October, 1977
Negative: Rhode Island Historical Preservation
Commission

Detail view of Victorian oak pew, installed
as part of the 1887 remodeling.

OCT 10 1978

Photo #5



Portsmouth Friends Meeting House
Portsmouth, Rhode Island

NOV 28 1978

Warren Jagger, Photographer October, 1977
Negative: Rhode Island Historical Preservation
Commission

Interior view south in eastern gallery, showing
early nineteenth-century pew and early eighteenth-
century or late seventeenth-century framing.

OCT 10 1978

Photo #6