

Danny Hurt 1979 Alabama Historical Commission

1. View from northwestfacade and west elevation of house

FEB 4 1982



Danny Hurt 1979 Alabama Historical Commission

2. View from east, showing eastern elevation

FEB 4 1982



Danny Hurt 1979 Alabama Historical Commission

3. View from south-showing rear or south elevation

FEB 4 1982



Danny Hurt 1979 Alabama Historical Communission

4. Interior view showing flush board wall and panëled dado

FEB 4 1982



Danny Hurt 1979 Alabama Historical Commission

5. Interior view corner stair leading from original portion of house to attic

FEB 4 1982 JAN 6 - 1982



Danny Hurt 1979 Alabama Historical Commission

6. Interior view Attic showing log construction

FEB 4 1982 JAN 6 - 1982



Unknown 1930's Library of Congress

7. View from northeast, showing north facade and east elevation in the 1930's. FEB 4 1982