



PROPERTY NAME : Brooks McCabe Residences  
LOCATION : 1223 Staunton Road  
Charleston WV

PHOTO CREDIT : Alice Carter

DATE OF PHOTO : July '83

NEGATIVE FILED AT : DEPT. OF CULTURE & HISTORY,  
HISTORIC PRESERVATION UNIT, THE CULTURAL CENTER,  
CAPITOL COMPLEX, CHARLESTON, W.VA. 25305

DESCRIPTION OF PHOTO : East facade

DIRECTION OF PHOTO : West



PROPERTY NAME : "Dalgain", Brooks McCabe Residence  
LOCATION : 1223 Staunton Road  
Charleston WV 25304

PHOTO CREDIT : Alice E Carter

DATE OF PHOTO : July 1983

NEGATIVE FILED AT : DEPT. OF CULTURE & HISTORY,  
HISTORIC PRESERVATION UNIT, THE CULTURAL CENTER,  
CAPITOL COMPLEX, CHARLESTON, W.VA. 25035

DESCRIPTION OF PHOTO :

Northeast section

DIRECTION OF PHOTO : Southwest