

KENTUCKY HISTORIC RESOURCES INVENTORY

Tm-M-15  
Site No. \_\_\_\_\_

1. Historic Name(s)  Original Owner _____		22. ADD County <u>No. Ky. / Trimble</u> <span style="float:right; border: 1px solid black; padding: 2px;">1 1 2</span>	
2. Present Name <u>Ginn's Furniture Store</u>		23. U.S.G.S. Quadrant (15'/75') <u>Madison East</u> <span style="float:right; border: 1px solid black; padding: 2px;"> </span>	
3. Location <u>State Highway 36 in Milton</u>		24. UTM Reference Zone _____ Easting _____ Northing _____	
4. Owner's Name <u>George Young</u>		25. Coordinate Accuracy <span style="float:right; border: 1px solid black; padding: 2px;"> </span>	
5. Owner's Address <u>804 East First Street, Madison, Indiana</u>		26. Prehistoric Site _____ Object _____ Historic Site _____ Structure _____ (Building) _____ Other _____	
6. Open to Public Yes <input checked="" type="checkbox"/> No _____	7. Visible from road Yes <input checked="" type="checkbox"/> No _____	8. Ownership Private _____ <input checked="" type="checkbox"/> Local _____ <input type="checkbox"/> State _____ <input type="checkbox"/> Federal _____ <input type="checkbox"/>	
9. Local Contact/Organization _____		27. National Register District Name: <u>Historic Resources of Trimble County</u> <span style="float:right; border: 1px solid black; padding: 2px;"> </span>	
10. Site Plan with North Arrow		28. Significance Evaluation <u>National Register</u> <span style="float:right; border: 1px solid black; padding: 2px;">D</span>	
18. Description <u>A two-story brick commercial building located in Milton on the Ohio River. Fenestration is six-bay with two entrances in side bays, both of which have three-pane transoms mounted vertically. Facade windows are 1-pane and 2/2 pane with two pane transoms. Brickwork consists of common bond with a row of headers every seven rows. Second floor windows are 2/2 pane. All bays have limestone lintels and</u>		11. Architect _____	
		12. Builder _____	
		13. Date <u>last qtr. of 19th Cent.</u> <span style="float:right; border: 1px solid black; padding: 2px;">5</span> B <input type="checkbox"/>	
		14. Style A. <input type="checkbox"/> B. <input type="checkbox"/>	
		15. Original Use <u>Commercial</u> <span style="float:right; border: 1px solid black; padding: 2px;">E</span>	
		16. Present use <u>Commercial</u>	
		17. Condition <u>Good</u> <span style="float:right; border: 1px solid black; padding: 2px;">B</span>	
19. History		29. Status _____ Date _____ National Landmark _____ National Register _____ Landmark Certificate _____ Kentucky Survey _____ Local Landmark _____ HABS HAER _____	
20. Significance <u>Architecture: The structure is the most architecturally significant buildings in Milton.</u>		30. Historic Theme Primary <u>Architecture</u> <span style="float:right; border: 1px solid black; padding: 2px;">C</span> Secondary <u>Commercial</u> <span style="float:right; border: 1px solid black; padding: 2px;">E</span> Other _____	
21. Source of Information		31. Endangered Yes _____ No <input checked="" type="checkbox"/>	
		32. Preservation Project Status <span style="float:right; border: 1px solid black; padding: 2px;"> </span>	
		Actual Cost in \$1,000s <span style="float:right; border: 1px solid black; padding: 2px;"> </span>	
		33. ATTACH PHOTO  Roll No. <u>40</u> Picture No. <u>25 - 36</u> Direction _____	
		34. Prepared by: <u>William Gus Johnson</u> <u>Sr. Historian &amp; Photographer</u>	
		35. Organization <u>Kentucky Heritage Council</u>	
		36. Date <u>Fall 1982</u>	
		37. Revision Dates _____ 38. Staff Review _____	

18. sills. The building is supported by a limestone foundation, and has interior gable-end chimneys. A bracketed cornice enhances the facade. The sides are pierced by eight-bays. Interior features include the original pressed tin ceiling.