

WAKERS  
TAXIDERMIST



School of Industries/Department of Public Welfare  
W corner of Astor and I Streets  
Bellingham, Whatcom, Washington  
February 2003

Northwest facade facing Astor Street  
Artifacts Consulting, Inc.  
Photo No. 1 of 15

TAXIDERMIST

KEEP OUT

School of Industries / Department of Public Welfare  
W corner of Astor and I Streets

Bellingham, Whatcom, Washington

February 2003

Southeast facade facing I Street

Artifacts Consulting, Inc.

Photo No. 2 of 15



School of Industries / Department of Public Welfare  
W corner of Astor and I Streets  
Bellingham, Whatcom, Washington

February 2003

First floor main volume looking Southeast  
Artifacts Consulting, Inc.  
Photo No. 3 of 15



School of Industries/Department of Public Welfare  
W corner of Astor and I Streets  
Bellingham, Whatcom, Washington  
February 2003

First floor main volume looking Southeast at stage  
Artifacts Consulting, Inc.  
Photo No. 4 of 15



School of Industries/Department of Public Welfare  
W corner of Astor and I Streets  
Bellingham, Whatcom, Washington

February 2003

First floor main volume looking Northwest

Artifacts Consulting, Inc.

Photo No. 5 of 15



School of Industries/Department of Public Welfare  
W corner of Astor and I Streets  
Bellingham, Whatcom, Washington  
February 2003

North stairwell looking down from second floor  
Artifacts Consulting, Inc.  
Photo No. 6 of 15



School of Industries/Department of Public Welfare  
W corner of Astor and I Streets  
Bellingham, Whatcom, Washington

February 2003

Second floor east volume looking east

Artifacts Consulting, Inc.

Photo No. 7 of 15



School of Industries / Department of Public Welfare

W corner of Astor and I Streets

Bellingham, Whatcom, Washington

February 2003

Second floor East volume looking South along central partition wall

Artifacts Consulting, Inc.

Photo No. 8 of 15



EXIT

School of Industries/Department of Public Welfare  
W corner of Astor and I Streets  
Bellingham, Whatcom, Washington  
February 2003

Second floor East volume looking Northwest  
Artifacts Consulting, Inc.  
Photo No. 9 of 15



School of Industries / Department of Public Welfare  
W corner of Astor and I Streets

Bellingham, Whatcom, Washington

February 2003

Second floor of central projection looking Southeast  
Artifacts Consulting, Inc.

Photo No. 10 of 15



School of Industries / Department of Public Welfare  
W corner of Astor and I Streets  
Bellingham, Whatcom, Washington  
February 2003

Second floor of central projection looking Northwest,  
particle board in immediate foreground covers  
former stairway

Artifacts Consulting, Inc.  
Photo No. 11 of 15



School of Industries/Department of Public Welfare  
W corner of Astor and I Streets  
Bellingham, Whatcom, Washington

February 2003

Radiator detail

Artifacts Consulting, Inc.

Photo No. 12 of 15



AKERS

TAXIDERMIST

AKERS  
TAXIDERMIST

School of Industries/Department of Public Welfare  
W corner of Astor and I Streets

Bellingham, Whatcom, Washington

February 2003

Three-quarter view of Southeast and Northeast facades

Artifacts Consulting, Inc.

Photo No. 13 of 15



TAXIDERMIST

AKERS

TAXIDERMIST

School of Industries/Department of Public Welfare

W corner of Astor and I Streets

Bellingham, Whatcom, Washington

February 2003

Three-quarter view of partial Southwest and full Southeast facades

Artifacts Consulting, Inc.

Photo No. 14 of 15



School of Industries/Department of Public Welfare  
W corner of Astor and I Streets

Bellingham, Whatcom, Washington

February 2003

Detail of Southwest foundation wall

Artifacts Consulting, Inc.

Photo No. 15 of 15