



McDermott House, ca. 1905

1100 South Street

Vicksburg, Mississippi 39180

Facade, north elevation

February 5, 1984

Clinton I. Bagley

P. O. Box 1332

Greenville, MS 38702-1332



McDermott House , ca. 1905
1100 South Street
Vicksburg, Ms 2/5/84

east elevation, and facade
looking southwest

Photo credit: Clint Bagley

Box 1332

Greenville, Ms. 38702-
1332



McDermott House, ca. 1905
1100 South Street
Vicksburg, Mississippi 39180

Stairway, west wall

February 5, 1984

Clinton I. Bagley

P. O. Box 1332

Greenville, MS 38702-1332



McDermott House, ca. 1905

1100 South Street

Vicksburg, Mississippi 39180

Parlor mantelpiece, east wall

February 5, 1984

Clinton I. Bagley

P. O. Box 1332

Greenville, MS 38702-1332



McDermott House, ca. 1905
1100 South Street
Vicksburg, MS 39180

Entrance hallway, mantelpiece and
west wall

February 5, 1984

Clinton I. Bagley
P. O. Box 1332
Greenville, MS 38702-1332



McDermott House, ca. 1905

1100 South Street

Vicksburg, Ms 2-5-84

Parlor & entrance to hallway Floor.

photo credit: Clint Bagley

Box 1332

Greenivlle, Ms 38702



Planters Hall

Yicksburg, Warren Co., MS

Brenda Rubach

July 1988

Mississippi Dept. of Archives & History

Facade (East elevation) of Kitchen

(note carriage house/stable to
left & Planters Hall to right),

view to southwest

Photo 1 of 2



100-11
100-12
100-13

Planters Hall

Vicksburg, Warren Co., MS

Brenda Rubach

July 1988

Mississippi Dept. of Archives & History

Facade (east) + south elevation of
Carriage house / stable (note
Planters Hall to right + Kitchen
roof to rear), view to northwest

Photo 2 of 2