McDermott House, ca. 1905
1100 South Street
Vicksburg, Mississippi 39180

Facade, north elevation

February 5, 1984

Clinton I. Bagley
P. O. Box 1332
Greenville, MS 38702-1332

McDermott House , ca. 1905
1100 SOuth Street
Vicksburg, Ms 2/5/84

east elevation, and facade
looking southwest
Photo credit: Clint Bagley
Box 1332
Greenville, Ms.38702-
1332

McDermott House, ca. 1905
1100 South Street
Vicksburg, Mississippi 39180

Stairway, west wall

February 5, 1984

Clinton I. Bagley
P. O. Box 1332
Greenville, MS 38702-1332

McDermott House, ca. 1905
1100 South Street
Vicksburg, Mississippi 39180

Parlor mantlepiece, east wall

February 5, 1984

Clinton I. Bagley
P. O. Box 1332
Greenville, MS 38702-1332

McDermott House, ca. 1905
1100 South Street
Vicksburg, MS 39180

Entrance hallway, mantlepiece and west wall

February 5, 1984

Clinton I. Bagley
P. O. Box 1332
Greenville, MS 38702-1332

McDermott House, ca. 1905
1100 South Street
Vicksburg, Ms 2-5-84

Parlor & entrance to hallway Floor.
photo credit: Clint Bagley
Box 1332
Greenivlle, Ms 38702

Planters Hall
Vicksburg, Warren Co., MS
Brenda Rubach
July 1988
Mississippi Dept. of Archives & History
Facade (East elevation) of Kitchen
(note Carriage house/stable to
left & Planters Hall to right),
view to southwest
Photo 1 of 2

Planters Hall
Vicksburg, Warren Co., MS
Brenda Rubach
July 1988
Mississippi Dept. of Archives & History
Facade (east) + South elevation of
Carriage house / stable (note
Planters Hall to right + Kitchen
roof to rear), view to northwest
Photo 2 of 2