

Name: Fisher Homestead (Cedwrcroft Farm) Sussex co. OCT 1 6 1979 Location: Southeast side of Oyster Rocks Road Photographer: Richard Carter Date: Sept, 1978 - June, 1979 Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901 Description: View of front and west gable end of Mid-19th Century House

DEC | | 1980

Photograph Number: 1 of 13



- Name: Fisher Homestead (Cedarcroft Farm)
- Location: Southeast side of Oyster Rocks Road Photographer: Richard Carter Date: Sept, 1978 - June, 1979 Location of Negative: Div. of Historical & Cultural Affairs, Ø/A&HP, Hall of Records, Dover, Delaware 19901 Description: View of west gable end showing pilasters; and second floor window added circa 1900
- Photograph Number: 2 of 13

DEC 1 1 1980



Sussex ca.

Location: Southeast side of Oyster Rocks Road

Photographer: Richard Carter Date: Sept, 1978 - June, 1979 Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901 Description: View of rear of house showing one story kitchen wing, enclosed porch and 2nd floor bathroom addition. Garage right foreground power house right center.

Photograph Number: 3 of 13

DEC 1 1 1980



Name: Fisher Homestead (Cedarcroft Farm) OCT 161979 Sussex Col. Location: Southeast side of Oyster Rocks Road Photographer: Richard Carter Date: Sept, 1978 - June, 1979 Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901 Description: View of center hall from parlor

Photograph Number: 4 of 13

DEC I I 1980



Name: Fisher Homestead (Cedarcroft Farm) Sussex CO. OCT 16 1979 Location: Southeast side of Oyster Rocks Road Photographer: Richard Carter Date: Sept, 1978 - June, 1979 Location of Negative: Div. of Historical & Cultural Affairs, B/AsHP, Hall of Records, Dover, Delaware 19901 Description: View of parlor fireplace

Photograph Number: 5 of 13



Name: Fisher Homestead (Cedarcroft Farm) OCT 1 6 1979 Susser co. Location: Southeast side of Oyster Rocks Road Photographer: Richard Carter Date: Sept, 1978 - June, 1979 Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901 Description: View of dining room and small office (formerly first-floor bedroom).

DEC

Photograph Number: 6 of 13



Name: Fisher Homestead (Cedarcroft Farm) Location: Southeast side of Oyster Rocks Road Photographer: Richard Carter Date: Sept, 1978 - June, 1979 Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901 Description: Original kitchen corner cupboard

Photograph Number: 7 of 13



Location: Southeast side of Oyster Rocks Road

Photographer: Richard Carter Date: Sept, 1978 - June, 1979 Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901 Description: View of large covered dining room fireplace.

DFC II

Photograph Number: 8 of 13



Location: Southeast side of Oyster Rocks Road

Photographer: Richard Carter Date: Sept, 1978 - June, 1979 Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901 Description: Privy

Photograph Number: 9 of 13

DEC I I 1980



Name: Fisher Homestead (Cedarcroft Farm) Sussex 10. OCT 1 6 1979 Location: Southeast side of Oyster Rocks Road

Photographer: Richard Carter Date: Sept, 1978 - June, 1979 Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901 Description: Milkhouse

Photograph Number: 10 of 13



Location: Southeast side of Oyster Rocks Road

Photographer: Richard Carter Date: Sept, 1978 - June, 1979 Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901 Description: View from front yard of house across hay marshes.

DECI

Photograph Number: 11 of 13



Location: Southeast side of Oyster Rocks Road

Photographer: Richard Carter Date: Sept, 1978 - June, 1979 Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901 Description: Monument erected at site of family cemetery

Photograph Number: 12 of 13



Name: Fisher Homestead (Cedarcroft Farm OCT 1 6 1979 Suppex CO. Location: Southeast side of Ovster Rocks Road Photographer: Richard Carter Date: Sept, 1978 - June, 1979 Location of Negative: Div. of Historical & Cultural Affairs, B/A&HP, Hall of Records, Dover, Delaware 19901 Description Monument erected at site of Mid-18th Century House.

Photograph Number: 13 of 13