


KENTUCKY HISTORIC RESOURCES INVENTORY

Site No. 4152

1. Historic Name(s) <u>Stone house on Indian Creek</u>		22. ADD/County <u>Bluegrass, Harrison</u>	
Original Owner <u>Haveland?</u>		23. U.S.G.S. Quadrant (15'/75') <u>Cynthiana vic.</u> G.I.S. Mod.	
2. Present Name <u>Deer Cheloland farm?</u>		24. UTM Reference <u>16 738160 4255560</u>	
3. Location <u>3/4 mi W of 62 on S. bank Indian Creek</u>		Zone Easting Northing	
4. Owner's Name <u>Mrs. Jimmy Clelland</u>		25. Coordinate Accuracy <input type="checkbox"/>	
5. Owner's Address <u>Route 2, Cynthiana, Ky. 41031</u>		26. Prehistoric Site Object Historic Site Structure Building <input checked="" type="checkbox"/> Other	
6. Open to Public Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	7. Visible from road Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	27. National Register District Name:	
8. Ownership Private <input checked="" type="checkbox"/> Local <input type="checkbox"/> State <input type="checkbox"/> Federal <input type="checkbox"/>		28. Significance Evaluation <input type="checkbox"/>	
9. Local Contact/Organization		29. Status Date National Landmark <input type="checkbox"/> National Register <input type="checkbox"/> Landmark Certificate <input type="checkbox"/> Kentucky Survey <input type="checkbox"/> Local Landmark <input type="checkbox"/> HABS/HAER <input type="checkbox"/>	
10. Site Plan with North Arrow <u>see attached boundary form</u>		30. Historic Theme Primary <u>architecture</u> <input checked="" type="checkbox"/> Secondary <input type="checkbox"/> Other <input type="checkbox"/>	
11. Architect		31. Endangered Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> <u>by neglect</u>	
12. Builder		32. Preservation Project Status <input type="checkbox"/>	
13. Date <u>brick ca 1810 stone ca 1830</u> A. <input checked="" type="checkbox"/> B. <input checked="" type="checkbox"/>		Actual Cost in \$1,000s <input type="checkbox"/>	
14. Style A. <u>Federal</u> <input checked="" type="checkbox"/> B. <u>Fed - G.R.</u> <input checked="" type="checkbox"/>		33. ATTACH PHOTO <u>in attached envelope</u>	
15. Original Use <u>residence</u> <input checked="" type="checkbox"/>		Roll No. _____	
16. Present use <u>vacant</u>		Picture No. _____	
17. Condition <u>poor</u> <input checked="" type="checkbox"/>		Direction _____	
18. Description <u>1 1/2 story 5 bay center passage brick house with 2 room dry stone wing. all addition, and 1 room stone kitchen. Brick house has pegged frames, raked jamba, 8 panel doors, chair rail. Horizontal bars w. mullions on cellar windows (over)</u> (Continue on Back)		34. Prepared by: <u>C. M. Woolley</u>	
No. Stories <u>1 1/2</u> <input checked="" type="checkbox"/>		35. Organization _____	
Single Pile <input checked="" type="checkbox"/> NA _____		36. Date <u>1982</u>	
Double Pile _____		37. Revision Dates _____ 38. Staff Review _____	
Floor Plan <u>brick: center passage</u> <input checked="" type="checkbox"/>			
Structural Fabric <u>brick, stone</u> A. <input checked="" type="checkbox"/> B. <input checked="" type="checkbox"/>			
Decorative Fabric A. <input type="checkbox"/>			
B. <u>ashlar masonry</u> <input checked="" type="checkbox"/> <u>brassiers</u>			
Roof Form <u>gable and hipped</u>			
19. History <u>Said to be one of three stone houses built by a Frenchman for his children. The others are #4150, on Haveland Lane, and a now demolished house on White Lane.</u>			
20. Significance <u>Well detailed early brick house with large stone addition.</u>			
21. Source of Information <u>inspection</u>			

18. cont.:

Enclosed corner stair arises from front of hall, space taken from N.W. room, as at Sc 141. Exterior chimney each end, press in E room beside fireplace. Two rooms on W end both served by the same chimney, corner fireplaces in each room; fine reeded breakfast sunburst mantel in SW room follows the turn of the wall.



(photo 2)

A 2 room stone wing was added on the E. end of the house, deeper than the house, and forming an ell. This addition has a hipped roof at the corner, gable on rear; 2 windows in N. front, exterior chimney on S rear. Double faced trim, diagonal trim chair rail, 4 panel doors, diagonal window trim. Cooping fireplace in cellar, entered from N.E. corner. Horizontal bars on cellar w.o. mullions. Wing has superior masonry on front, (photo 4) 9 stone voussiers, typical tooling. No voussiers on cellar windows has allowed wall above to fall out.

(photo 3)

South of the stone wing-ell is an additional stone room with exterior chimney on S. end. Better doors, lift latches.

Porches span the length of the additions on the E. and W, W. porch makes ell and extends to rear door of brick house. (see plan)

The stone additions were painted brick red. House faces N., built on S. bank of Indian Creek.

VERBAL BOUNDARY DESCRIPTION & JUSTIFICATION

Beginning at A, at a fence, and at a point directly N of the stone ell, thence parallel to rear wall of house W 150 ft to B, thence at right angle N to the creek bank (C) thence with creek bank E. 250 ft to D, thence parallel to B-C to the fence (E) thence with fence 100 ft W. to the beginning, containing the brick house and stone additional - about 1.4 acre.

to 62

SKETCH MAP OF SITE SHOWING BOUNDARIES AND KEY BUILDINGS AND FEATURES WITH NORTH ARROW.

