



(HOUSE)

4 SEP 1979

Lewis Residence (preferred)  
Minn-Kota Red Cross Chapter Office  
Fargo, North Dakota, *Cass County*

Photo credit: Jacqueline Sluss

Date of photo: July, 1978

Location of negative: State Historical Society of North Dakota  
Liberty Memorial Building  
Bismarck, North Dakota 58505

Facade, looking south.

Photo 1 of 8

*DOE*  
OCT 18 1979



(House)

Lewis Residence (preferred)  
Minn-Kota Red Cross Chapter Office  
Fargo, North Dakota, *Cass County*

4 SEP 1979

Photo credit: Jacqueline Sluss

Date of photo: July, 1978

Location of negative: State Historical Society of North Dakota  
Liberty Memorial Building  
Bismarck, North Dakota

Rear of building, looking north.

Photo 2 of 8

*DOE*  
OCT 18 1979





*(House)*

Lewis Residence (preferred)  
Minn-Kota Red Cross Chapter Office  
Fargo, North Dakota *(Cass County)*

**4 SEP 1979**

Photo credit: Jacqueline Sluss

Date of photo: July, 1978

Location of negative: State Historical Society of North Dakota  
Liberty Memorial Building  
Bismarck, North Dakota 58505

Vestibule with oak coffered wall paneling and stained glass windows.

Photo 3 of 8

*DOE*

OCT 18 1979



(House)

4 SEP 1979

Lewis Residence (preferred)  
Minn-Kota Red Cross Chapter Office  
Fargo, North Dakota, *Casa County*

Photo credit: Jacqueline Sluss

Date of photo: July, 1978

Location of negative: State Historical Society of North Dakota  
Liberty Memorial Building  
Bismarck, North Dakota 58505

Living room.

Photo 4 of 8

*DOE*

OCT 18 1979





(House)  
Lewis Residence (preferred)  
Minn-Kota Red Cross Chapter Office  
Fargo, North Dakota, *Cass County*

4 SEP 1979

Photo credit: Jacqueline Sluss  
Date of photo: July, 1978  
Location of negative: State Historical Society of North Dakota  
Liberty Memorial Building  
Bismarck, North Dakota 58505

West side, looking northeast.

Photo 5 of 8

DOE  
OCT 18 1979



4 SEP 1979

Lewis Residence (preferred)  
Minn-Kota Red Cross Chapter Office  
Fargo, North Dakota, *Cass County*

Photo credit: Jacqueline Sluss

Date of photo: July, 1978

Location of negative: State Historical Society of North Dakota  
Liberty Memorial Building  
Bismarck, North Dakota 58505

Northwest corner of kitchen, showing blond oak cabinets and wall wainscoting.

Photo 6 of 8

*DOE*  
OCT. 18 1979





(House)

Lewis Residence (preferred)  
Minn-Kota Red Cross Chapter Office  
Fargo, North Dakota, *CASS County*

**4 SEP 1979**

Photo credit: Jacqueline Sluss

Date of photo: July, 1978

Location of negative: State Historical Society of North Dakota  
Liberty Memorial Building  
Bismarck, North Dakota 58505

Stained glass windows near second floor staircase landing.

Photo 7 of 8

*bottom*

*DOE*  
**OCT. 18 1979**

the  
good neighbor

the  
good neighbor



(House)

4 SEP 1979

Lewis Residence (preferred)  
Minn-Kota Red Cross Chapter Office  
Fargo, North Dakota, *Cass County*

Photo credit: Jacqueline Sluss

Date of photo: July, 1978

Location of negative: State Historical Society of North Dakota  
Liberty Memorial Building  
Bismarck, North Dakota 58505

Ballroom fireplace, showing brass fire box with wreath and festoon motifs.

Photo 8 of 8

*DOE*  
OCT 18 1979