



Photograph #1
Turn-of-River Bridge, Stamford, CT
Northwest View
Steven Bedford, January 1986
Negative on file at Connecticut Historical Commission

APR 24 1987



Photograph #2

Turn-of-River Bridge, Stamford, CT

Detail of Upper Cord of Truss

Steven Bedford, January 1986

Negative on file at Connecticut Historical Commission



Photograph #3

Turn-of-River Bridge, Stamford, CT

Northwest View of Northerly Truss

Steven Bedford, January 1986

Negative on file at Connecticut Historical Commission



Photograph #4

Turn-of-River Bridge, Stamford, CT

Detail of Pin-hanger Connection, Southerly Truss

Steven Bedford, January 1986

Negative on file at Connecticut Historical Commission



Photograph #5

Turn-of-River Bridge, Stamford, CT

View of Deck Beam and Stringers

Steven Bedford, January 1986

Negative on file at Connecticut Historical Commission



Photograph #6

Turn-of-River Bridge, Stamford, CT

Southeast View of Southerly Abutment

Steven Bedford, January 1986

Negative on file at Connecticut Historical Commission



Photograph #7

Turn-of-River Bridge, Stamford, CT

Southwest View

Steven Bedford, January 1986

Negative on file at Connecticut Historical Commission



Photograph #8

Turn-of-River Bridge, Stamford, CT

Southeast View

Steven Bedford, January 1986

Negative on file at Connecticut Historical Commission



Photograph #9

Turn-of-River Bridge, Stamford, CT

Northwest View of Southerly Truss

Steven Bedford, January 1986

Negative on file at Connecticut Historical Commission

APR 24 1987