



Donahoe House - 1981

Ponca City, Oklahoma

Jim Richey - 302 S 7

Ponca City OK 74601

1) Front (east) from E

FEB 5 - 1982



Donahoe House - 1981

Ponca City, Oklahoma

Jim Richey - 302 S 7

Ponca City OK 74601

2) North side from NE



Donahoe House - 1981

Ponca City, Oklahoma

Jim Richey - 302 S 7

Ponca City OK 74601

3) View from SW - Sleeping

Porch added c. 1917,

South wing c. 1920

FEB 5 - 1982



Donahoe House - 1981

Ponca City, Oklahoma

Jim Richey - 302 S 7

Ponca City OK 74601

4) View from SSE FEB 5 - 1982



Donahoe House - 1981

Ponca City, Oklahoma

Jim Richey - 302 S 7

Ponca City OK 74601

5) Porch Details - columns,
cast concrete planters,
limestone steps and caps,
decorative rafter ends

5 - 1982

FEB



Donahoe House - 1981

Ponca City, Oklahoma

Jim Richey - 302 S 7

Ponca City OK 74601

6) Porch column FEB 5 - 1982



Donahoe House - 1981

Ponca City, Oklahoma

Jim Richey - 302 S 7

Ponca City OK 74601

7) Fireplace - note beaten
brass hood, craftsman-
andirons

FEB 5 - 1982



Donahoe House - 1981

Ponca City, Oklahoma

Jim Richey - 302 S 7

Ponca City OK 74601

8) View from library into dining room. Woodwork in den unpainted - in all other rooms painted. All doors similar to this one - hinged and sliding. FEB 5 - 1982



Donahoe House - 1981

Ponca City, Oklahoma

Jim Richey - 302 S 7

Ponca City OK 74601

9) brass and copper light
fixture in library

FEB 5 - 1982



Donahoe House - 1981

Ponca City, Oklahoma

Jim Richey - 302 S 7

Ponca City OK 74601

10) Staircase. All wood-

work is oak FEB 5 - 1982




Donahoe House - 1981

Ponca City, Oklahoma

Jim Richey - 302 S 7

Ponca City OK 74601 FEB 5 - 1982

11) Upstairs detail



Donahoe House - 1981

Ponca City, Oklahoma

Jim Richey - 302 S 7

Ponca City OK 74601

12) Master bath FEB 5 . 1982



Donahoe House - 1981

Ponca City, Oklahoma

Jim Richey - 302 S 7

Ponca OK 74601

13) Second bath added
in 1920. Note tooth-
brush sink. FEB 5 . 1982