



Condition of track + paving -

Grand Ave btwn. Belmont + E. Morrison looking north

NATHANIEL WEST BUILDINGS
711-727 SE Grand Avenue
Portland, Multnomah Co., Oregon
1 of 10

Historic photo, looking north, n.d.
nominated buildings on upper left.
Oregon Historical Society photo
1230 SW Park Avenue
Portland, Oregon 97205

THIS PHOTOPRINT IS ISSUED
FOR REFERENCE USE ONLY
PERMISSION FOR EACH
REPRODUCTION MUST BE
REQUESTED.

Oregon Historical Society
1230 SW PARK AVENUE
PORTLAND, OREGON 97205

NEGATIVE NUMBER:

PG 130-30

#1673



NATHANIEL WEST BUILDINGS
711-727 SE Grand Avenue
Portland, Multnomah Co., Oregon
2 of 10

Photo of principal facade of BOTH buildings facing East. Photo taken from the S.E. corner of Grand & Morrison.

June, 1982 (Photo taken prior to 727 remodeling.) 727 S.E. Grand, Portland, OR 97214



NATHANIEL WEST BUILDINGS

711-721 SE Grand Avenue

Portland, Multnomah Co., Oregon

3 of 10

Photo of principal facade of building prior to remodelling. Note tile work on lower half of building.

Photo taken June, 1982

Negative held at 727 S. E. Grand Avenue
Portland, Oregon 97214



NATHANIEL WEST BUILDINGS
711-727 SE Grand Avenue
Portland, Multnomah Co., Oregon
4 of 10

Photo of principal facade of entire Grand Ave.
Block, facing East. Note partially visible
advertisement.

June, 1982, (Photo prior to remodelling.
Negative held at 727 S.E. Grand Ave., Portland
Oregon 97214



NATHANIEL WEST BUILDINGS

711-727 SE Grand Avenue

Portland, Multnomah Co., Oregon

5 of 10

Principal facade facing East, Corner of Grand
& Morrison Streets, S.E.

August, 1982 (Photo reflects building under
remodelling construction)

727 S.E. Grand Ave., Portland, Ore. 97214



NATHANIEL WEST BUILDINGS

711-727 SE Grand Avenue

Portland, Multnomah Co., Oregon

6 of 10

View of back of both buildings, windows looking West, photo taken from S.W. corner of Union Avenue.

June 1982 (Phot was taken prior to 721-727 remodelling).

Negative held at 727 S.E. Grand Avenue
Portland, Oregon 97214



NATHANIEL WEST BUILDINGS

711-727 SE Grand Avenue

Portland, Multnomah Co., Oregon

7 of 10

Photo of interior of main floor. Note brick wall dividing two main rooms of floor and antique refurbishings.

June, 1982

Negative held at 727 S.E. Grand Avenue,
Portland, Oregon 97214



NATHANIEL WEST BUILDINGS

711-727 SE Grand Avenue

Portland, Multnomah Co., Oregon

8 of 10

Interior view of main floor of 727 reflecting brick walls and archway which at one time had been filled in with brick.

June, 1982 (Photo taken prior to remodelling of principal facade)

Negative held at 727 S. E. Grand Avenue,
Portland, Oregon 97214



NATHANIEL WEST BUILDINGS

711-727 SE Grand Avenue

Portland, Multnomah Co., Oregon

9 of 10

Interior view of second floor of 727 building.

Note stairway banister.

June, 1982

Negative held at 727 S.E. Grand Avenue,
Portland, Oregon 97214



NATHANIEL WEST BUILDINGS

711-727 SE Grand Avenue

Portland, Multnomah Co., Oregon

10 of 10

View of second floor of 727 building. Note brick work, prominent throughout all buildings, and bricked-in fireplace with chimney.

June 1982, Negative held at 727 S.E. Grand Avenue, Portland, Oregon 97214