



Photograph A

MAY 29 1979 #1

St. Elmo, Colorado

Taken from the east boundary

looking southwesterly

across the town to the

SEP 17 1979 mountains beyond the
boundaries, Structure

#16, the Town Hall,
stands in the center.

Photographer: Douglas W. Hagen

January 30, 1978

Negative in possession of the
photographer

St. Elmo Hist. Dist.
Chaffee County

08/03/0007/03



MINERS
EXCHANGE

THOUSE

Photograph B
St. Elmo, Colorado

JAN 29 1978

#2

St. Elmo Hist. Dist.,
Chaffee County

Taken from a short distance
south of Main St. looking
northeasterly to struc-
tures #7 (left) and #6
(right), the Miners Ex-
change Building.

Photographer: Douglas W. Hagen
January 30, 1978
Negative in possession of the
photographer

SEP 17 1979

09/03/0007/03



STARA BWA POST OFFICE

SEP 17 1979
Photograph C
St. Elmo, Colorado

Taken from a short distance
south of Main St. looking
northwesterly toward the

most concentrated area of
buildings. The Stark
Hotel (structure #13)
dominates the center of
the photograph.

Photographer: Douglas W. Hagen

January 30, 1978

Negative in possession of the
photographer

#3

St. Elmo Hist. Dist.
Chaffee County

08/03/0007/03



Photograph D-1
St. Elmo, Colorado

#4

Taken near the corner of Main and
1st streets looking westerly
along Main St. and showing
structures #11, #12, #13,
#14, and #15.

Photographer: Douglas W. Hagen

January 30, 1978

Negative in possession of the
photographer

MAY 29 1979

St. Elmo Hist. Dist.
Chaffee County

08/03/2007/03



ST. ELMO
FIRE CO.
CITY HALL

Photographer E
St. Elmo, Colorado

MAY 29 1979

#5 St. Elmo Hist. Dist.
Chaffee County

Taken from Main St. looking
southwesterly to
structures #16 (The

Town Hall), #17 (The
Log Cabin Duplex), and #18
(the Annabelle Stark Ward
Cabin).

Photographer: Douglas W. Hagen
January 30, 1978

SEP 17 1979

Negative in possession of the
photographer

03/03/0007/03



Photograph F

MAY 29 1979

#6

St. Elmo, Colorado

Taken from Main St. looking
northeasterly at the
Stark Hotel (#13) and
structure #12. Note the
wooden sidewalk.

Photographer: Douglas W. Hagen
January 30, 1978

Negative in possession of the
photographer

SEP 17 1979

St. Elmo Hist. Dist.
Chaffee County



Photograph G
St. Elmo, Colorado
Taken from Main St. looking
south at the Pink Cabin
(#19) and the Harrison
Cabin (#20).

MAY 29 1979 #17
SEP 17 1979

St. Elmo Hist. Dist.
Chaffee County

Photographer: Douglas W. Hagen
January 30, 1978
Negative in possession of the
photographer

08/03/0007/03



Photograph H
St. Elmo, Colorado

MAY 29 1979

#8

Taken from the corner of Main
and 1st streets looking
northwesterly across Chalk
Creek toward the back of
structures #26 and #27
both of which front on Gun-
nison St.

SEP 17 1979

Photographer: Douglas W. Hagen

1 January 30, 1978

7 Negative in possession of the
photographer

St. Elmo Hist. Dist.
Chaffee County



Photograph I

St. Elmo, Colorado

Taken from the junction of 1st
Street and Chalk Creek
looking easterly toward
the backs of structures
#8, #7, and #6 and the
north and west facades
of structures #3 and #4.
Part of the east boundary
lies beyond.

Photographer: Douglas W. Hagen
January 30, 1979

Negative in possession of the
photographer

#9

MAY 29 1979

St. Elmo Hist. Dist.
Chaffee County

SEP 17 1979



Photograph J

St. Elmo, Colorado

Taken from the junction of 1st Street and Chalk Creek looking westerly along the Creek at the extreme left and the backs of structures #26, #27, #28, #29, and #30. The west boundary of the district lies in the distance.

MAY 29 1979
SEP 17 1979

Photographer: Douglas W. Hagen
January 30, 1978

Negative in possession of the
photographer

#10 St. Elmo Hist. Dist.
Chaffee County

03/03/0007/03



Photograph K

St. Elmo, Colorado

Taken from the intersection of
Gunnison and Pitkin
streets looking south-
easterly along Gunnison
St. to structure #29
(right) and structure #28
(left), the Wilks Cabin.

Photographer: Douglas W. Hagen
January 30, 1978

Negative in possession of the
photographer

MAY 29 1978

#11

St Elmo Hist. Dist
Chaffee County

SEP 17 1979



Photograph L

St. Elmo, Colorado

Taken from 1st Street looking
northwesterly to the
school (structure #38) and
the north boundary of the
district which lies beyond.

Photographer: Douglas W. Hagen

January 30, 1978

Negative in possession of the
photographer

SEP 17 1979

MAY 29 1979 #12

St. Elmo Hist. Dist.
Chaffee County



Photograph M
St. Elmo, Colorado

Taken from Pitkin Street looking northwesterly to structures #42 and #43 and showing part of the west boundary of the district in the background.

Photographer: Douglas W. Hagen
January 30, 1978

Negative in possession of the
photographer

MAY 29 1979

#13

St. Elmo Hist. Dist.
Chaffee County

SEP 17 1979



Photograph of Structure #23 #14
(Marie's Cabin)

SEP 17 1979

St. Elmo, Colorado

Taken from Main St. looking
southwesterly.

Photographer: Howard L.

Meredith

August, 1978

MAY 29 1979

Negative in possession of the
photographer

St. Elmo Hist. List,
Chaffee County



ST ELMO
FIRE CO
CITY HALL

KEEP OUT

Photograph of Structure #16 **#15**
(the Town Hall) SEP 17 1979
St. Elmo, Colorado

Taken from the Stark Hotel
(structure #13) looking
south and showing the
southern boundary of the
district in the back-
ground.

Photographer: Howard L.
Meredith

August 1978

MAY 29 1979

Negative in possession of the
photographer

*St. Elmo Hist. Dist.
Chaffee County*



Photograph of Structure #1 #16
(Barn and Livery Stable)

St. Elmo, Colorado

Taken from the intersection of
Main and Poplar Streets
looking northerly

Photographer: Howard L.
Meredith

August 1978

Negative in possession of the
photographer

MAY 29 1979

SEP 17 1979

St. Elmo Hist. Dist.
Chaffee County



Photograph of Structure #2
St. Elmo, Colorado
Taken from Poplar St. looking
northwesterly

Photographer: Howard L.
Meredith

August 1978

Negative in possession of
the photographer

#17 St. Elmo Hist. Dist.
Chaffee County

SEP 17 1979

MAY 29 1979



Photograph of Structure #32 #18
(Log Duplex) SEP 17 1979

St. Elmo, Colorado

Taken from Gunnison St. looking
southeasterly

Photographer: Howard L.
Meredith

August 1978

Negative in possession of
the photographer

St. Elmo Hist. Dist.
Chaffee County



Photograph of Structure #14 ~~#14~~ #19
(the Canteen) and one-
story house now attached
to and part of Structure
#13 (the Stark Hotel)

St. Elmo, Colorado

Taken from Main Street looking
north

Photographer: Howard L.
Meredith

August 1978

MAY 29 1979

Negative in possession of the
photographer

St. Elmo Hist. Dist.
Chaffee County



Photograph D-2

SEP 17 1979

#20

St. Elmo, Colorado

Taken near the corner of Main
and 1st streets looking
westerly along Main Street
and showing structures #11,
#12, #13, #14, and #15

Photographer: Howard L.

Meredith

August 1978

Negative in possession of the
photographer

St. Elmo Hist. Dist.
Chaffee County



PRIVATE
PROPERTY
NO TRESPASSING

8

Photograph of Structure #27 #21
St. Elmo, Colorado
Taken from Gunnison St. facing
south

Photographer: Howard L.
Meredith
August 1978
Negative in possession of the
photographer

SEP 17 1979

MAY 29 1979

St. Elmo Hist. Dist.
Chaffee County