

TRIMBORN FARM, 8801 W. Grange Ave., Greendale, Milwaukee Co., WI, 1979. Photo by Terry Shoptaugh. Neg. at State Historical Society of Wis. View from southeast showing, 1 to r, old sheds, stone barn, silos, and stable. Supplemental photo #1 of **%** .



TRIMBORN FARM. 8801 W. Grange Ave.. Greendale, Milwaukee Co., WI, 1979. Photo by Terry Shoptaugh. Neg. at State Historical Society of Wis. Stable, photographed from north. Supplemental Photo #2/9+3.




TRIMBORN FARM, 8801 W. Grange Ave., Greendale, Milwaukee Co., WI, 1979. Photo by Terry Shoptaugh, Neg. at State Historical Society of Wis. Remains of smokehouse photographed from SW. Supplemental photo #3/7of 3. JUL 3 1 1980




TRIMBORN FARM. 8801 W. Grange Ave., Greendale, Milwaukee Co., WI, 1979. Photo by Terry Shoptaugh. Neg. at WI Hist. Society. Farmhouse viewed from west. Photo #4 of 4/7 MAY 2 0 1980



TRIMBORN FARM, 8801 W. Grange Ave., Greendale, Milwaukee County, WI. Photo by Terry Shoptaugh, 1979. Neg. at WI Hist. Society. South lime kiln photographed from northeast. Photo ## # 5/-, MAY 2 0 1980



TRIMBORN FARM. 8801 W. Grange Ave., Greendale, Milwaukee Co., WI. Photo by Terry Shoptaugh, 1979. Neg. at WI Hist. Society. Stone Barn photographed from northeast. Photo #3 of 4. 9 MAY 2 0 1980



MAY 2 U 1980 TRIMBORN FARM, 8801 W. Grange Ave.. Greendale, Milwaukee Co., WI, 1979. Photo by Terry Shoptaugh. Neg. at WI Hist. Society. Bunkhouse photographed from north. Photo #2-06-7/2