




80-A-1

Hoag Gristmill & Knight House Complex
Starksboro, Vermont *Addison CO.*
Credit: Charles Ashton
Date: December 1979 *APR 22 1980*
Negative filed at Vermont Division for Historic Preservation
Description: Hoag Gristmill (Left, #1) & Knight House (Right, #2). Overall view looking west.
FEB 20 1980



Hoag Gristmill & Knight House Complex
Starksboro, Vermont

Credit: Peter Hawley

Date: October 1979

Negative filed at Vermont Division for
Historic Preservation

Description: Lewis Creek & Hoag Gristmill
looking east.

Photograph #2 01/7 FEB 20 1980

Addison Co.
APR 22 1980



Hoag Gristmill & Knight House Complex
Starksboro, Vermont

Credit: Peter Hawley *Addison Co.*

Date: October 1979

Negative filed at Vermont Division for
Historic Preservation

Description: Hoag Gristmill entrance facade
looking north.

Photograph #3 *of 17*

FEB 20 1980



80-A-1

Hoag Gristmill & Knight House Complex
Starksboro, Vermont *Addison Co.*
Credit: Charles Ashton
Date: December 1979
Negative filed at Vermont Division for
Historic Preservation
Description: Knight House (#2), looking
northwest.
Photograph #4 of 17 FEB 20 1980



80-A-1

Hoag Gristmill & Knight House Complex
Starksboro, Vermont
Credit: Charles Ashton *Addison Co.*
Date: December 1979
Negative filed at Vermont Division for
Historic Preservation
Description: Knight House (#2), door detail.
Photograph #5 of 17 **FEB 20 1980**



80-A-1

Hoag Gristmill & Knight House Complex
Starksboro, Vermont

Credit: Charles Ashton

Addison co.

Date: December 1979

APR 22 1980

Negative filed at Vermont Division for
Historic Preservation

Description: Hog Barn (L #4) and Hay Barn/
Stable (R #3). View looking north across Lewis

Photograph #6 *tr* Creek.

FEB 20 1980