

Location: Looking NE at W and S elevations

Copy Negative :

Heritage Investment Corporation 123 NW Second Avenue #200 Portland, Oregon 97209

John Tess Photographer 1992

<u>/</u> of <u>//</u>



Location: Looking E at W elevation

Copy Negative :

Heritage Investment Corporation 123 NW Second Avenue #200 Portland, Oregon 97209

John Tess Photographer 1992





Location: Looking SE at W and N elevations

Copy Negative :

Heritage Investment Corporation 123 NW Second Avenue #200 Portland, Oregon 97209

John Tess Photographer 1992

 $\frac{3}{2}$  of  $\frac{17}{2}$ 



Location: Looking NW at the E and S Elevations

Copy Negative :

Heritage Investment Corporation 123 NW Second Avenue #200 Portland, Oregon 97209

John Tess Photographer 1992



Location: Exterior detail -- Main Entrance

Copy Negative :

Heritage Investment Corporation 123 NW Second Avenue #200 Portland, Oregon 97209

John Tess Photographer 1992



Location: Foyer

Copy Negative :

Heritage Investment Corporation 123 NW Second Avenue #200 Portland, Oregon 97209

John Tess Photographer 1992



Location: Foyer

Copy Negative :

Heritage Investment Corporation 123 NW Second Avenue #200 Portland, Oregon 97209

John Tess Photographer 1992



Location: Interior detail -- Telephone System

Copy Negative :

Heritage Investment Corporation 123 NW Second Avenue #200 Portland, Oregon 97209

John Tess Photographer 1992



Location: Interior Detail, Tile Floor in Foyer

Copy Negative :

Heritage Investment Corporation 123 NW Second Avenue #200 Portland, Oregon 97209

John Tess Photographer 1992



Location: Interior Detail, Main Stair

Copy Negative :

Heritage Investment Corporation 123 NW Second Avenue #200 Portland, Oregon 97209

John Tess Photographer 1992



Location: Interior Detail, Window

Copy Negative :

Heritage Investment Corporation 123 NW Second Avenue #200 Portland, Oregon 97209

John Tess Photographer 1992



Location: Interior Detail, Main Stair looking down

Copy Negative :

Heritage Investment Corporation 123 NW Second Avenue #200 Portland, Oregon 97209

John Tess Photographer 1992



Location: Apartment dining room

Copy Negative :

Heritage Investment Corporation 123 NW Second Avenue #200 Portland, Oregon 97209

John Tess Photographer 1992



Location: Interior Detail, Apartment Interior Window

Copy Negative :

Heritage Investment Corporation 123 NW Second Avenue #200 Portland, Oregon 97209

John Tess Photographer 1992



Location: Interior detail, Built-in Sideboard

Copy Negative :

Heritage Investment Corporation 123 NW Second Avenue #200 Portland, Oregon 97209

John Tess Photographer 1992



Location: Apartment Kitchen

Copy Negative :

Heritage Investment Corporation 123 NW Second Avenue #200 Portland, Oregon 97209

John Tess Photographer 1992



Location: Apartment Bedroom

Copy Negative :

Heritage Investment Corporation 123 NW Second Avenue #200 Portland, Oregon 97209

John Tess Photographer 1992