

80-4-267

City Hall Park Historic District Burlington, Vermont Credit: John C. Page Date: December, 1980

Negative Filed at Vermont Division for

Historic Preservation

Description: City Hall Park, looking northeast from the corner of Main and St. Paul Streets Photograph 1



80-A-267

City Hall Park Historic District
Burlington, Vermont
Credit: John C. Page
Date: December, 1980
Negative Filed at Vermont Division for
Historic Preservation
Description: City Hall Park, looking north
from the corner of Main and St. Paul Streets
Photograph 2



City Hall Park Historic District Burlington, Vermont

Credit: Gina Campoli Date: January, 1983

Negative Filed at Vermont Division for

Historic Preservation

Description: West side of Church Street,

(L to R) #'s 17, 11, 10, 9, 8

Photograph 3

83-A-2



City Hall Park Historic District
Burlington, Vermont
Credit: Gina Campoli
Date: January, 1983
Negative Filed at Vermont Division for
Historic Preservation
Description: South side of Main Street, (L to
R) #'s 17, 16, 15, 14, 13, 12
Photograph 4



City Hall Park Historic District
Burlington, Vermont
Credit: John C. Page
Date: December, 1980
Negative Filed at Vermont Division for
Historic Preservation
Description: West side of Church Street, (L to
R) #'s 24, 23, 22, 21, 20, 19, 18
Photograph 5



2445

City Hall Park Historic District
Burlington, Vermont
Credit: Gina Campoli
Date: January, 1983
Negative Filed at Vermont Division for
Historic Preservation
Description: (L) Burlington Trust Company
Building, #2; (R) Second Merchants Bank, #1;
View looking Northwest
Photograph 6



City Hall Park Historic District
Burlington, Vermont
Credit: Gina Campoli
Date: January, 1983
Negative Filed at Vermont Division for
Historic Preservation
Description: (L) Burlington Savings Bank, #5;
(C) Burlington Savings Bank Annex, #4; (R)
Crispin Leather, #3; View looking Northeast
Photograph 7



77-4-178

City Hall Park Historic District
Burlington, Vermont
Credit: Mitchell Grubler
Date: June, 1977
Negative Filed at Vermont Division for
Historic Preservation
Description: Burlington Savings Bank, #5;
View looking Northeast
Photograph 8




City Hall Park Historic District
Burlington, Vermont
Credit: John C. Page
Date: December, 1980
Negative Filed at Vermont Division for
Historic Preservation
Description: St. Paul Street Annex of the
Burlington Savings Bank, #6; View looking
Northeast
Photograph 9



Burlington, Vermont
Credit: Gina Campoli
Date: January, 1983
Negative Filed at Vermont Division for


Historic Preservation

Description: McAuliffe Building, #8; View looking Southwest Photograph 10



83-A-2

City Hall Park Historic District
Burlington, Vermont
Credit: Gina Campoli
Date: January, 1983
Negative Filed at Vermont Division for
Historic Preservation
Description: Merchants Bank, #9; View looking
Southwest
Photograph 11



83-4-2

City Hall Park Historic District
Burlington, Vermont
Credit: Gina Campoli
Date: January, 1983
Negative Filed at Vermont Division for
Historic Preservation
Description: City Hall, #11, Church Street
facade; View looking Northwest
Photograph 12



Burlington, Vermont Credit: Gina Campoli Date: January, 1983

Date: January, 1983 Negative Filed at Vermont Division for

Historic Preservation


Description: Hotel Vermont, #12; View looking

Southwest Photograph 13



83-41

City Hall Park Historic District
Burlington, Vermont
Credit: Gina Campoli
Date: January, 1983
Negative Filed at Vermont Division for
Historic Preservation
Description: East wing of the American House,
#13; View looking Southwest
Photograph 14




Burlington, Vermont Credit: Gina Campoli Date: January, 1983

Negative Filed at Vermont Division for


Historic Preservation

Description: Flynn Theater, #14; View looking

Southwest Photograph 15 83-A-/



City Hall Park Historic District
Burlington, Vermont
Credit: Gina Campoli
Date: January, 1983
Negative Filed at Vermont Division for
Historic Preservation
Description: Commercial Block at 155-159 Main
Street, #15; View looking Southwest
Photograph 16



83-A-2

City Hall Park Historic District
Burlington, Vermont
Credit: Gina Campoli
Date: January, 1983
Negative Filed at Vermont Division for
Historic Preservation
Description: Times Building, #17; View looking
Southwest
Photograph 17



83-A-1

City Hall Park Historic District
Burlington, Vermont
Credit: Gina Campoli
Date: January, 1983
Negative Filed at Vermont Division for
Historic Preservation
Description: (L) Stacy House, #19; (R) Stacy
Livery Stable, #18; View looking Southwest
Photograph 18



City Hall Park Historic District Burlington, Vermont Credit: Gina Campoli

Date: January, 1983

Negative Filed at Vermont Division for

Historic Preservation

Description: (L) Charlies Red Hots, #21; (R) Fresh Ground Coffee House, #20; View looking

Northwest Photograph 19 83-A-1



Burlington, Vermont Credit: Gina Campoli Date: January, 1983

Negative Filed at Vermont Division for

Historic Preservation

Description: Asahel Peck House, #22; View

looking Southwest

Photograph 20

1



83-4-1

City Hall Park Historic District
Burlington, Vermont
Credit: Gina Campoli
Date: January, 1983
Negative Filed at Vermont Division for
Historic Preservation
Description: Wilson Block, #23; View looking
Southwest
Photograph 21



83-1-1

City Hall Park Historic District

Burlington, Vermont Credit: Gina Campoli Date: January, 1983

Negative Filed at Vermont Division for

Historic Preservation

Description: Mills House (Wilson Hotel), #24;

View looking Southwest

Photograph 22



Burlington, Vermont Credit: Gina Campoli Date: January, 1983

Negative Filed at Vermont Division for

Historic Preservation

Description: Mills House (Wilson Hotel), #24;

View looking Northwest

Photograph 23

James Jose E. B.